

Plasterboard fire lining

No obvious steel beams in 3D survey, SE to confirm

C. Section through door threshold with FFL +10.067 at no.75