

Balfour Beatty
Construction

SUB-CONTRACTOR SITE INSTRUCTION

Contract:- CDC Hackney

Instruction No.:

Name of Sub-Contractor

Contract No. CLK10066

129

RCL

Description of Work to be Carried Out:-

Remove and refix door frames due to partition not built big enough in all toilets cubicles 3rd 2nd and 1st floors nr lift shaft

Date:- 23/11/07

Time:- 9:58:42 AM

BB Authorising Signature: - M. Nevshehir

S/C Receiving Signature:-

Note:- Where the Instruction constitutes a variation under the Contract, payment terms will be agreed by the Quantity Surveyor.