



## WEEKLY PLANT RETURN

### AND

## PLANT SAFETY CHECK

**SITE:** Manhattan loft gardens

**COMPILED & CHECKED BY:** G.BUCK

**WEEK ENDING:** 17-03-2019

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u> | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u> |
|-------------------|-----------------|---------------------|----------------------|-------------------------|-------------------------------------------|
| CHOPSAW           | 785             | 13/08/18            |                      | 05/05/19                |                                           |
| SKILLSAW          | 664             | 13/08/18            |                      | 05/05/19                |                                           |
| JIGSAW            | 666             | 13/08/18            |                      | 05/05/19                |                                           |
| PISTOL DRILL      | 888A            | 13/08/18            |                      | 05/05/19                |                                           |
| HAMMER DRILL      | 894             | 13/08/18            |                      | 05/05/19                |                                           |
| AIR COMPRESSER    | 1262            | 13/08/18            |                      | 05/05/19                |                                           |
| HOOVER            | 1344            | 13/08/18            |                      | 05/05/19                |                                           |
| LEAD              | 930             | 13/08/18            |                      | 05/05/19                |                                           |
| LEAD              | 1319            | 13/08/18            |                      | 05/05/19                |                                           |
| LEAD              | 1253            | 13/08/18            |                      | 05/05/19                |                                           |
| LEAD              | 211             | 13/08/18            |                      | 05/05/19                |                                           |
| TOOLBOX           | 3A              | 13/08/18            |                      |                         |                                           |
| TOOLBOX           | 23A             | 13/08/18            |                      |                         |                                           |
| PODIUM            | PS13            | 13/08/18            |                      |                         |                                           |
| A FRAME TROLLEY   | 120             | 13/08/18            |                      |                         |                                           |
| TOOLBOX           | 1342            | 15/10/18            |                      |                         |                                           |
| TOOLBOX           | 1343            |                     |                      |                         |                                           |

|                                        |                   |             |     |                                                            |                                 |             |
|----------------------------------------|-------------------|-------------|-----|------------------------------------------------------------|---------------------------------|-------------|
| DOCUMENT REFERENCE:<br>DOCUMENT OWNER: | SIT-FM-011<br>DAS | VERSION NO: | 1.0 | CREATION DATE:<br>LAST REVISION DATE:<br>NEXT REVIEW DATE: | 07/02/2013<br>N/A<br>07/02/2014 | Page 1 of 1 |
|----------------------------------------|-------------------|-------------|-----|------------------------------------------------------------|---------------------------------|-------------|





## WEEKLY PLANT RETURN

AND

## PLANT SAFETY CHECK

**SITE: Wembley Block  
W03**

**COMPILED & CHECKED BY: A. Kulsinskas**

**WEEK ENDING 17/03/19**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u>      | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/<br/>other comments</u> |
|------------------------|-----------------|---------------------|----------------------|-------------------------|-----------------------------------------------|
| Toolbox                | 1026            | 05/03/2018          |                      | N/A                     | Condition good                                |
| Toolbox                | 1A              | 05/03/2018          |                      | N/A                     | Condition good                                |
| Toolbox                | 1340            | 04/05/2018          |                      | N/A                     | Condition good                                |
| Toolbox                | 16A             | 01/08/2018          |                      | N/A                     | Condition good                                |
| Toolbox                | 29A             | 01/08/2018          |                      | N/A                     | Condition good                                |
| Toolbox                | 4A              | 03/09/2018          |                      | N/A                     | Condition good                                |
| Toolbox                | 9A              | 19/10/2018          |                      | N/A                     | Condition good                                |
| 110v Lead              | 211             | 04/05/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 1317            | 04/05/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 1267            | 04/05/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 1245            | 04/05/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 1247            | 05/03/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 932             | 05/03/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 268             | 01/08/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 1356            | 01/08/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 83              | 24/09/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 104             | 24/09/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Lead              | 897             | 24/09/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Splitter Box      | 265             | 05/03/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Splitter Box      | 643             | 04/05/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Splitter Box      | 2662            | 19/10/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Task Light        | 1304            | 04/05/2018          |                      | 20/03/2019              | Condition good                                |
| 110v Task Light        | 1360            | 19/10/2018          |                      | 20/03/2019              | Condition good                                |
| Dust Control Extractor | 1243            | 01/08/2018          |                      | 20/03/2019              | Condition good                                |
| Dust Control Extractor | 1264            | 21/08/2018          |                      | 20/03/2019              | Condition good                                |
| Dust Control Extractor | 1242            | 29/08/2018          |                      | 20/03/2019              | Condition good                                |
| Dust Control Extractor | 1353            | 05/11/2018          |                      | 20/03/2019              | Condition good                                |
| Makita Router ¼        | 63              | 05/03/2018          |                      | 20/03/2019              | Condition good                                |
| Makita Router ½        | 67              | 05/04/2018          |                      | 20/03/2019              | Condition good                                |
| Makita Router ¼        | 1353            | 04/07/2018          |                      | 20/03/2019              | Condition good                                |
| Makita Router ¼        | 959             | 06/08/2018          |                      | 20/03/2019              | Condition good                                |
| Dewalt Router ¼        | 1357            | 06/08/2018          |                      | 20/03/2019              | Condition good                                |
| Dewalt Router ½        | 892             | 24/09/2018          |                      | 20/03/2019              | Condition good                                |

|                     |            |             |     |                     |            |             |
|---------------------|------------|-------------|-----|---------------------|------------|-------------|
| DOCUMENT REFERENCE: | SIT-FM-011 | VERSION NO: | 1.1 | CREATION DATE:      | 07/02/2013 |             |
| DOCUMENT OWNER:     | DAS        |             |     | LAST REVISION DATE: | 04/07/2013 | Page 1 of 1 |
|                     |            |             |     | NEXT REVIEW DATE:   | 07/02/2014 |             |

|                                 |      |            |  |            |                |
|---------------------------------|------|------------|--|------------|----------------|
| 2 <sup>nd</sup> Fix Paslode Gun | 529  | 05/03/2018 |  | N/A        | Condition good |
| 2 <sup>nd</sup> Fix Paslode Gun | 169  | 04/05/2018 |  | N/A        | Condition good |
| 2 <sup>nd</sup> Fix Paslode Gun | 1336 | 15/08/2018 |  | N/A        | Condition good |
| 2 <sup>nd</sup> Fix Paslode Gun | 1255 | 17/09/2018 |  | N/A        | Condition good |
| 2 <sup>nd</sup> Fix Paslode Gun | 1360 | 20/09/2018 |  | N/A        | Condition good |
| Makita Chopsaw                  | 940  | 01/08/2018 |  | 20/03/2019 | Condition good |
| Makita Chopsaw                  | 957  | 18/09/2018 |  | 20/03/2019 | Condition good |
| Makita Jigsaw                   | 1275 | 05/03/2018 |  | 20/03/2019 | Condition good |
| Bosch Jigsaw                    | 48   | 05/04/2018 |  | 20/03/2019 | Condition good |
| Jigsaw                          | 1276 | 04/05/2018 |  | 20/03/2019 | Condition good |
| Makita Skillsaw                 | 706  | 05/03/2018 |  | 20/03/2019 | Condition good |
| Bosch Skillsaw                  | 790  | 05/04/2018 |  | 20/03/2019 | Condition good |
| Makita Skillsaw                 | 1043 | 04/05/2018 |  | 20/03/2019 | Condition good |
| Bosch Planer                    | 905  | 05/03/2018 |  | 20/03/2019 | Condition good |
| Makita Planer                   | 912  | 05/03/2018 |  | 10/04/19   | Condition good |
| Makita Planer                   | 942  | 04/05/2018 |  | 20/03/2019 | Condition good |
| Makita Hammer Drill             | 913  | 05/03/2018 |  | 20/03/2019 | Condition good |
| Makita Sds                      | 361  | 04/05/2018 |  | 20/03/2019 | Condition good |
| Multi Tool                      | 1280 | 04/05/2018 |  | 20/03/2019 | Condition good |
| Makita Biscuit cutter           | 936  | 05/04/2018 |  | 20/03/2019 | Condition good |
| A Frame                         |      | 04/05/2018 |  | N/A        | Condition good |
| A Frame                         | 1294 | 24/09/2018 |  | N/A        | Condition good |
| Printer Epson                   |      | 17/09/2018 |  | 20/03/2019 | Condition good |
| Tea Kettle                      |      | 17/09/2018 |  | 20/03/2019 | Condition good |



## WEEKLY PLANT RETURN

AND

## PLANT SAFETY CHECK

**SITE: OXFORD STRET**

**COMPILED & CHECKED BY : K.Kulsinskas**

**WEEK ENDING: 17/03/19**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u>           | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u> |
|-----------------------------|-----------------|---------------------|----------------------|-------------------------|-------------------------------------------|
| TOOL BOX                    | 25              | 08/02/19            |                      | N/A                     |                                           |
| 110 V LEAD                  | 930             | 08/02/19            |                      | 14/05/19                |                                           |
| 110 V LEAD                  | 1300            | 08/02/19            |                      | 14/05/19                |                                           |
| 110 V LEAD                  | 1009            | 08/02/19            |                      | 14/05/19                |                                           |
| 110 V SPLITTER BOX          | 1227            | 08/02/19            |                      | 14/05/19                |                                           |
| 110 V SPLITTER BOX          | 272             | 08/02/19            |                      | 14/05/19                |                                           |
| 110 V SPLITTER BOX          | 69              | 08/02/19            |                      | 14/05/19                |                                           |
| DUST CONTROL EXTRACTOR UNIT | 1303            | 08/02/19            |                      | 14/05/19                |                                           |
| MAKITA SKILLSAW             | 918             | 08/02/19            |                      | 14/05/19                |                                           |
| BOSCH HAMMER DRILL          | 1329            | 08/02/19            |                      | 14/05/19                |                                           |
| MAKITA HAMMER DRILL         | 360             | 08/02/19            |                      | 14/05/19                |                                           |
| DEWALT CHOPSAW              | 334             | 08/02/19            |                      | 14/05/19                |                                           |
| ToolBox                     | A2              | 08/03/19            |                      | N/A                     |                                           |
| Makita planer               | 619             | 08/03/19            |                      | 07/06/19                |                                           |
| Bosh jigsaw                 | 633             | 08/03/19            |                      | 07/06/19                |                                           |
| ¼ Router                    | 1208            | 08/03/19            |                      | 07/06/19                |                                           |
|                             |                 |                     |                      |                         |                                           |
|                             |                 |                     |                      |                         |                                           |
|                             |                 |                     |                      |                         |                                           |
|                             |                 |                     |                      |                         |                                           |

|                     |            |             |     |                     |            |             |
|---------------------|------------|-------------|-----|---------------------|------------|-------------|
| DOCUMENT REFERENCE: | SIT-FM-011 | VERSION NO: | 1.1 | CREATION DATE:      | 07/02/2013 | Page 1 of 1 |
| DOCUMENT OWNER:     | DAS        |             |     | LAST REVISION DATE: | 04/07/2013 |             |
|                     |            |             |     | NEXT REVIEW DATE:   | 07/02/2014 |             |



## WEEKLY PLANT RETURN

AND

## PLANT SAFETY CHECK

**SITE: OXFORD STRET**

**COMPILED & CHECKED BY : K.Kulsinskas**

**WEEK ENDING: 17/03/19**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u>           | <u>I.D. No.</u> | <u>On Site<br/>Date</u> | <u>Off Site<br/>Date</u> | <u>Test<br/>Expiry Date</u> | <u>Condition of items/<br/>other comments</u> |
|-----------------------------|-----------------|-------------------------|--------------------------|-----------------------------|-----------------------------------------------|
| TOOL BOX                    | 25              | 08/02/19                |                          | N/A                         |                                               |
| 110 V LEAD                  | 930             | 08/02/19                |                          | 14/05/19                    |                                               |
| 110 V LEAD                  | 1300            | 08/02/19                |                          | 14/05/19                    |                                               |
| 110 V LEAD                  | 1009            | 08/02/19                |                          | 14/05/19                    |                                               |
| 110 V SPLITTER BOX          | 1227            | 08/02/19                |                          | 14/05/19                    |                                               |
| 110 V SPLITTER BOX          | 272             | 08/02/19                |                          | 14/05/19                    |                                               |
| 110 V SPLITTER BOX          | 69              | 08/02/19                |                          | 14/05/19                    |                                               |
| DUST CONTROL EXTRACTOR UNIT | 1303            | 08/02/19                |                          | 14/05/19                    |                                               |
| MAKITA SKILLSAW             | 918             | 08/02/19                |                          | 14/05/19                    |                                               |
| BOSCH HAMMER DRILL          | 1329            | 08/02/19                |                          | 14/05/19                    |                                               |
| MAKITA HAMMER DRILL         | 360             | 08/02/19                |                          | 14/05/19                    |                                               |
| DEWALT CHOPSAW              | 334             | 08/02/19                |                          | 14/05/19                    |                                               |
| ToolBox                     | A2              | 08/03/19                |                          | N/A                         |                                               |
| Makita planer               | 619             | 08/03/19                |                          | 07/06/19                    |                                               |
| Bosh jigsaw                 | 633             | 08/03/19                |                          | 07/06/19                    |                                               |
| ¼ Router                    | 1208            | 08/03/19                |                          | 07/06/19                    |                                               |
|                             |                 |                         |                          |                             |                                               |
|                             |                 |                         |                          |                             |                                               |
|                             |                 |                         |                          |                             |                                               |
|                             |                 |                         |                          |                             |                                               |

|                     |            |             |     |                     |            |             |
|---------------------|------------|-------------|-----|---------------------|------------|-------------|
| DOCUMENT REFERENCE: | SIT-FM-011 | VERSION NO: | 1.1 | CREATION DATE:      | 07/02/2013 | Page 1 of 1 |
| DOCUMENT OWNER:     | DAS        |             |     | LAST REVISION DATE: | 04/07/2013 |             |
|                     |            |             |     | NEXT REVIEW DATE:   | 07/02/2014 |             |



## WEEKLY PLANT RETURN

### AND

## PLANT SAFETY CHECK

**SITE: WELLINGTON HOUSE**

**COMPILED & CHECKED BY: S Simonovic**

**WEEK ENDING: 17/03/19**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u>                    | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u> |
|--------------------------------------|-----------------|---------------------|----------------------|-------------------------|-------------------------------------------|
| TOOL BOX                             | 1341            | 30/01/19            |                      | N/A                     |                                           |
| TOOL BOX                             | 15A             | 30/01/19            |                      | N/A                     |                                           |
| SITE BOX                             | 32A             | 26/11/18            |                      | N/A                     |                                           |
| PLASTIC TRESTLES                     | N/A             | 30/01/19            |                      | N/A                     |                                           |
| 110V EXTENSION LEAD                  | 78A             | 20/11/18            |                      | 13/05/19                |                                           |
| 110V EXTENSION LEAD                  | 74              | 20/11/18            |                      | 13/05/19                |                                           |
| 110V EXTENSION LEAD                  | 83              | 20/11/18            |                      | 13/05/19                |                                           |
| 110V EXTENSION LEAD                  | 471             | 20/11/18            |                      | 13/05/19                |                                           |
| 110V EXTENSION LEAD                  | 1254            | 31/01/19            |                      | 13/05/19                |                                           |
| 110V EXTENSION LEAD                  | 1369            | 05/03/19            |                      | ---                     | New, to be tested (not in use)            |
| 110V SPLITTER BOX                    | 300             |                     |                      | 13/05/19                |                                           |
| 110V SPLITTER BOX                    | 1368            | 30/01/19            |                      | 13/05/19                |                                           |
| MAKITA SKILL SAW                     | 705             | 20/11/18            |                      | 13/05/19                |                                           |
| BOSCH PISTOL DRILL                   | 889B            | 20/11/18            |                      | 13/05/19                |                                           |
| DEWALT ¼ ROUTER                      | 1361            | 31/01/19            |                      | 13/05/19                |                                           |
| Dust extractor                       | 1363            | 30/01/19            |                      | 13/05/19                |                                           |
| DEWALT ½" ROUTER                     | 891A            | 08/02/19            |                      | 13/05/19                |                                           |
| DEWALT CHOPSAW                       | 795             | 08/02/19            |                      | 13/05/19                |                                           |
| MAKITA PLANER                        | 161             | 08/02/19            |                      | 13/05/19                |                                           |
| BOSCH JIGSAW                         | 726             | 08/02/19            |                      | 13/05/19                |                                           |
| BOSCH HAMMER DRILL                   | 934             | 05/03/19            |                      | 05/06/19                |                                           |
| MAKITA ½" ROUTER                     | PS22            | 11/02/19            |                      | 13/05/19                |                                           |
| DEWALT ¼" ROUTER                     | 660             | 11/02/19            |                      | 13/05/19                |                                           |
| PASLODE 2 <sup>nd</sup> fix (ANGLED) | 1014            | 05/03/19            |                      | N/A                     |                                           |
| THASK LIGHT                          | 1350            | 05/03/19            |                      | 20/03/19                |                                           |

|                                        |                   |             |     |                                                            |                                        |             |
|----------------------------------------|-------------------|-------------|-----|------------------------------------------------------------|----------------------------------------|-------------|
| DOCUMENT REFERENCE:<br>DOCUMENT OWNER: | SIT-FM-011<br>DAS | VERSION NO: | 1.1 | CREATION DATE:<br>LAST REVISION DATE:<br>NEXT REVIEW DATE: | 07/02/2013<br>04/07/2013<br>07/02/2014 | Page 1 of 1 |
|----------------------------------------|-------------------|-------------|-----|------------------------------------------------------------|----------------------------------------|-------------|



# WEEKLY PLANT RETURN

AND

# PLANT SAFETY CHECK

**SITE: AELTC**

**COMPILED & CHECKED BY : J. Wray**

**WEEK ENDING: 17/03/19**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u>               | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u>           |
|---------------------------------|-----------------|---------------------|----------------------|-------------------------|-----------------------------------------------------|
| TOOL BOX                        | 41A             | 29/11/18            |                      | N/A                     |                                                     |
| TOOL BOX                        | 1366            | 29/11/18            |                      | N/A                     |                                                     |
| 110 V LEAD                      | 1293            | 29/11/18            |                      | 28/05/19                |                                                     |
| 110 V LEAD                      | 1319            | 29/11/18            |                      | 28/05/19                |                                                     |
| 110 V LEAD                      | 1254            | 29/11/18            |                      | 28/05/19                |                                                     |
| 110 V LEAD                      | 158             | 29/11/18            |                      | 28/05/19                |                                                     |
| DUST CONTROL EXTRACTOR UNIT     | RCL1304         | 30/11/18            |                      | 30/05/19                |                                                     |
| MAKITA PISTOL DRILL             | 1003            | 29/11/18            |                      | 28/05/19                |                                                     |
| BOSCH JIGSAW                    | 162             | 29/11/18            |                      | 28/05/19                |                                                     |
| MAKITA SKILLSAW                 | 827             | 08/03/19            |                      | 07/06/19                |                                                     |
| MAKITA SKILLSAW                 | 622             | 28/02/19            | 08/03/19             | 28/05/19                | Loose cable / no power – Taken by Joe for repair    |
| BOSCH HAMMER DRILL              | 1040            | 29/11/18            |                      | 28/05/19                |                                                     |
| DEWALT CHOPSAW                  | 676             | 29/11/18            |                      | 28/05/19                |                                                     |
| MAKITA PLANER                   | 751             | 29/11/18            |                      | 28/05/19                | Pat test tag shows ID no 751 but 752 marked on tool |
| MAKITA BISCUIT JOINTER          | 244             | 29/11/18            |                      | 28/05/19                |                                                     |
| 110 V SPLITTER BOX              | 649             | 04/01/19            |                      | 28/05/19                |                                                     |
| MEDIUM PODIUM STEPS             | 363             | 04/01/19            |                      | N/A                     |                                                     |
| BOSCH ANGLE GRINDER 125mm       | 598             | 18/01/19            |                      | 28/05/19                |                                                     |
| MAKITA MULTI TOOL               | 1302            | 14/02/19            |                      | 13/05/19                |                                                     |
| DEWALT ¼ " ROUTER               | 1361            | 13/03/19            |                      | 13/05/19                |                                                     |
| EPSON Workforce WF-7610 PRINTER | WF7610          | 29/11/18            |                      | 28/05/19                |                                                     |

|                     |            |             |     |                     |            |             |
|---------------------|------------|-------------|-----|---------------------|------------|-------------|
| DOCUMENT REFERENCE: | SIT-FM-011 | VERSION NO: | 1.1 | CREATION DATE:      | 07/02/2013 | Page 1 of 1 |
| DOCUMENT OWNER:     | DAS        |             |     | LAST REVISION DATE: | 04/07/2013 |             |
|                     |            |             |     | NEXT REVIEW DATE:   | 07/02/2014 |             |