



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: AELTC

COMPILED & CHECKED BY: S. Simonovic

WEEK ENDING: 06/01/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	41A	29/11/18		19/02/19	
TOOL BOX	1366	29/11/18		19/02/19	
110 V LEAD	1293	29/11/18		19/02/19	
110 V LEAD	1319	29/11/18		19/02/19	
110 V LEAD	1254	29/11/18		19/02/19	
110 V LEAD	158	29/11/18		19/02/19	
110 V SPLITTER BOX	243	29/11/18	04/01/19	19/02/19	Damaged – Gone for Repair
DUST CONTROL EXTRACTOR UNIT	RCL1304	30/11/18		30/05/19	
MAKITA PISTOL DRILL	1003	29/11/18		19/02/19	
BOSCH JIGSAW	162	29/11/18		19/02/19	
MAKITA SKILLSAW	828	29/11/18		19/02/19	
BOSCH HAMMER DRILL	1040	29/11/18		19/02/19	
DEWALT CHOPSAW	676	29/11/18		19/02/19	
DEWALT 1/4" ROUTER	660	29/11/18		19/02/19	
MAKITA PLANER	751	29/11/18		19/02/19	
MAKITA BISCUIT JOINTER	244	29/11/18		06/06/18	NOT IN USE AT PRESENT
110 V SPLITTER BOX	649	04/01/19		03/12/18	Needs PAT testing
MEDIUM PODIUM STEPS	363	04/01/19		N/A	
EPSON Workforce WF-7610 PRINTER	WF7610	29/11/18		19/02/19	

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------