

WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Wembley Block
W03

COMPILED & CHECKED BY: A. Kulsinskas

WEEK ENDING 07/04/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	1026	05/03/2018		N/A	Condition good
Toolbox	1A	05/03/2018		N/A	Condition good
Toolbox	1340	04/05/2018		N/A	Condition good
Toolbox	16A	01/08/2018		N/A	Condition good
Toolbox	29A	01/08/2018		N/A	Condition good
Toolbox	4A	03/09/2018		N/A	Condition good
Toolbox	9A	19/10/2018		N/A	Condition good
110v Lead	211	04/05/2018		19/06/2019	Condition good
110v Lead	1317	04/05/2018	03/04/19	19/06/2019	Condition good
110v Lead	1267	04/05/2018		19/06/2019	Condition good
110v Lead	1245	04/05/2018	03/04/19	19/06/2019	Condition good
110v Lead	1247	05/03/2018		19/06/2019	Condition good
110v Lead	932	05/03/2018		19/06/2019	Condition good
110v Lead	268	01/08/2018		19/06/2019	Condition good
110v Lead	1356	01/08/2018		19/06/2019	Condition good
110v Lead	83	24/09/2018	03/04/19	19/06/2019	Condition good
110v Lead	104	24/09/2018		19/06/2019	Condition good
110v Lead	897	24/09/2018		19/06/2019	Condition good
110v Splitter Box	265	05/03/2018		19/06/2019	Condition good
110v Splitter Box	643	04/05/2018		19/06/2019	Condition good
110v Splitter Box	2662	19/10/2018		19/06/2019	Condition good
110v Task Light	1304	04/05/2018		19/06/2019	Condition good
110v Task Light	1360	19/10/2018		19/06/2019	Condition good
Dust Control Extractor	1243	01/08/2018		19/06/2019	Condition good
Dust Control Extractor	1264	21/08/2018		19/06/2019	Condition good
Dust Control Extractor	1242	29/08/2018	03/04/19	19/06/2019	Condition good
Dust Control Extractor	1353	05/11/2018		19/06/2019	Condition good
Makita Router ¼	63	05/03/2018		19/06/2019	Condition good
Makita Router ½	67	05/04/2018		19/06/2019	Condition good
Makita Router ¼	1353	04/07/2018		19/06/2019	Condition good
Makita Router ¼	959	06/08/2018		19/06/2019	Condition good
Dewalt Router ¼	1357	06/08/2018	03/04/19	19/06/2019	Condition good
Dewalt Router ½	892	24/09/2018		19/06/2019	Condition good

DOCUMENT REFERENCE:
DOCUMENT OWNER:

SIT-FM-011
DAS

VERSION NO:

1.1


CREATION DATE:
LAST REVISION DATE:
NEXT REVIEW DATE:

07/02/2013
04/07/2013
07/02/2014

Page 1 of 1

2 nd Fix Paslode Gun	529	05/03/2018	03/04/19	N/A	Condition good
2 nd Fix Paslode Gun	169	04/05/2018		N/A	Condition good
2 nd Fix Paslode Gun	1336	15/08/2018		N/A	Condition good
2 nd Fix Paslode Gun	1255	17/09/2018		N/A	Condition good
2 nd Fix Paslode Gun	1360	20/09/2018		N/A	Condition good
Makita Chopsaw	940	01/08/2018	03/04/19	19/06/2019	Condition good
Makita Chopsaw	957	18/09/2018		19/06/2019	Condition good
Makita Jigsaw	1275	05/03/2018		19/06/2019	Condition good
Jigsaw	1276	04/05/2018	03/04/19	19/06/2019	Condition good
Makita Skillsaw	706	05/03/2018	03/04/19	19/06/2019	Condition good
Bosch Skillsaw	790	05/04/2018	03/04/19	19/06/2019	Condition good
Makita Skillsaw	1043	04/05/2018		19/06/2019	Condition good
Makita Planer	912	05/03/2018		19/06/2019	Condition good
Makita Planer	942	04/05/2018	03/04/19	19/06/2019	Condition good
Makita Hammer Drill	913	05/03/2018	03/04/19	19/06/2019	Condition good
Bosch Battery Hammer Drill	E1	18/03/2019		N/A	Condition good
Makita Sds	361	04/05/2018		19/06/2019	Condition good
Multi Tool	1280	04/05/2018		19/06/2019	Condition good
Makita Biscuit cutter	936	05/04/2018		19/06/2019	Condition good
A Frame		04/05/2018		N/A	Condition good
A Frame	1294	24/09/2018		N/A	Condition good
Printer Epson		17/09/2018		19/06/2019	Condition good
Chain Mortiser	812	18/03/2019		19/06/2019	Condition good
Tea Kettle		17/09/2018		19/06/2019	Condition good

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 2 of 1
--	-------------------	-------------	-----	--	--	-------------



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Manhattan loft gardens

COMPILED & CHECKED BY: G.BUCK

WEEK ENDING: 07-04-2019


Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
CHOPSAW	785	13/08/18		05/05/19	
SKILLSAW	664	13/08/18		05/05/19	
JIGSAW	666	13/08/18		05/05/19	
PISTOL DRILL	888A	13/08/18		05/05/19	
HAMMER DRILL	894	13/08/18		05/05/19	
AIR COMPRESSER	1262	13/08/18		05/05/19	
HOOVER	1344	13/08/18		05/05/19	
LEAD	930	13/08/18		05/05/19	
LEAD	1319	13/08/18		05/05/19	
LEAD	1253	13/08/18		05/05/19	
LEAD	211	13/08/18		05/05/19	
TOOLBOX	3A	13/08/18			
TOOLBOX	23A	13/08/18			
PODIUM	PS13	13/08/18			
A FRAME TROLLEY	120	13/08/18			
TOOLBOX	1342	15/10/18			
TOOLBOX	1343				

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.0	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 N/A 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	---------------------------------	-------------



DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 2
--	-------------------	-------------	-----	--	--	-------------



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: WELLINGTON HOUSE

COMPILED & CHECKED BY: S Simonovic

WEEK ENDING: 07/04/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	1341	30/01/19		N/A	
TOOL BOX	15A	30/01/19		N/A	
SITE BOX	32A	26/11/18		N/A	
PLASTIC TRESTLES	N/A	30/01/19		N/A	
110V EXTENSION LEAD	78A	20/11/18		13/05/19	
110V EXTENSION LEAD	74	20/11/18		13/05/19	
110V EXTENSION LEAD	83	20/11/18		13/05/19	
110V EXTENSION LEAD	471	20/11/18		13/05/19	
110V EXTENSION LEAD	1254	31/01/19		13/05/19	
110V EXTENSION LEAD	1369	05/03/19		21/06/19	
110V SPLITTER BOX	300			13/05/19	
110V SPLITTER BOX	1368	30/01/19		13/05/19	
MAKITA SKILL SAW	705	20/11/18		13/05/19	
BOSCH PISTOL DRILL	889B	20/11/18		13/05/19	
Dust extractor	1363	30/01/19		13/05/19	
DEWALT ½" ROUTER	891A	08/02/19		13/05/19	
DEWALT CHOPSAW	795	08/02/19		13/05/19	
MAKITA PLANER	161	08/02/19		13/05/19	
BOSCH JIGSAW	726	08/02/19		13/05/19	
BOSCH HAMMER DRILL	934	05/03/19		05/06/19	
MAKITA ½" ROUTER	PS22	11/02/19		13/05/19	
DEWALT ¼" ROUTER	660	11/02/19		13/05/19	
PASLODE 2 nd fix (ANGLED)	1014	05/03/19		N/A	
THASK LIGHT	1350	05/03/19		21/06/19	

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: OXFORD STRET

COMPILED & CHECKED BY : K.Kulsinskas

WEEK ENDING: 07/04/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	25	08/02/19		N/A	
110 V LEAD	930	08/02/19		14/05/19	
110 V LEAD	1300	08/02/19		14/05/19	
110 V LEAD	1009	08/02/19		14/05/19	
110 V SPLITTER BOX	1227	08/02/19		14/05/19	
110 V SPLITTER BOX	272	08/02/19		14/05/19	
110 V SPLITTER BOX	69	08/02/19		14/05/19	
DUST CONTROL EXTRACTOR UNIT	1303	08/02/19		14/05/19	
MAKITA SKILLSAW	918	08/02/19		14/05/19	
BOSCH HAMMER DRILL	1329	08/02/19		14/05/19	
MAKITA HAMMER DRILL	360	08/02/19		14/05/19	
DEWALT CHOPSAW	334	08/02/19		14/05/19	
ToolBox	A2	08/03/19		N/A	
Makita planer	619	08/03/19		07/06/19	
Bosh jigsaw	633	08/03/19		07/06/19	
¼ Router	1208	08/03/19		07/06/19	

DOCUMENT REFERENCE:
DOCUMENT OWNER:

SIT-FM-011
DAS

VERSION NO:

1.1

CREATION DATE:
LAST REVISION DATE:
NEXT REVIEW DATE:

07/02/2013
04/07/2013
07/02/2014

Page 1 of 1



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: AELTC

COMPILED & CHECKED BY : J. Wray

WEEK ENDING: 07/04/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	41A	29/11/18		N/A	
TOOL BOX	1366	29/11/18		N/A	
110 V LEAD	1293	29/11/18		28/05/19	
110 V LEAD	1319	29/11/18		28/05/19	
110 V LEAD	1254	29/11/18		28/05/19	
110 V LEAD	158	29/11/18		28/05/19	
DUST CONTROL EXTRACTOR UNIT	RCL1304	30/11/18		30/05/19	
MAKITA PISTOL DRILL	1003	29/11/18		28/05/19	
BOSCH JIGSAW	162	29/11/18	03/04/19	28/05/19	Collected by Joe for repair Motor problems
BOSCH JIGSAW	1276	03/04/19		19/06/19	
MAKITA SKILLSAW	827	08/03/19		07/06/19	
BOSCH HAMMER DRILL	1040	29/11/18		28/05/19	
DEWALT CHOPSAW	676	29/11/18		28/05/19	
MAKITA PLANER	751	29/11/18		28/05/19	Pat test tag shows ID no 751 but 752 marked on tool
MAKITA BISCUIT JOINTER	244	29/11/18		28/05/19	
110 V SPLITTER BOX	649	04/01/19		28/05/19	
MEDIUM PODIUM STEPS	363	04/01/19		N/A	
BOSCH ANGLE GRINDER 125mm	598	18/01/19		28/05/19	
MAKITA MULTI TOOL	1302	14/02/19		13/05/19	
DEWALT 1/4" ROUTER	1361	13/03/19		13/05/19	
MAKITA METAL COLD CHOPSAW	1349	21/03/19	03/04/19	06/05/19	Collected by Joe
EPSON Workforce WF-7610 PRINTER	WF7610	29/11/18		28/05/19	