



WEEKLY PLANT RETURN

AND PLANT SAFETY CHECK

SITE: Manhattan loft gardens

COMPILED & CHECKED BY: G.BUCK

WEEK ENDING: 23-08

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition: other con</u>
CHOPSAW	785	13/08/18		03/08/19	
SKILLSAW	664	13/08/18		03/08/19	
JIGSAW	666	13/08/18	06/06/19	03/08/19	
PISTOL DRILL	888A	13/08/18		03/08/19	
HAMMER DRILL	894	13/08/18		03/08/19	
AIR COMPRESSOR	1262	13/08/18	06/06/19	03/08/19	
HOOVER	1344	13/08/18		03/08/19	
LEAD	930	13/08/18	06/06/19	03/08/19	
LEAD	1319	13/08/18		03/08/19	
LEAD	1253	13/08/18		03/08/19	
LEAD	211	13/08/18		03/08/19	
TOOLBOX	3A	13/08/18	06/06/19		
TOOLBOX	23A	13/08/18			
PODIUM	PS13	13/08/18	06/06/19		
A FRAME TROLLEY	120	13/08/18		15-06-19	
TOOLBOX	1342	15/10/18			
TOOLBOX	1343				

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.0	CREATION DATE:	07/02/2013	Page 1
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	N/A	
				NEXT REVIEW DATE:	07/02/2014	



PLANT SAFETY CHECK

SITE: MLG

COMPILED & CHECKED BY: G.BUCK

WEEK ENDING:23-0

[illegible]

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	Pag
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: WELLINGTON HOUSE

COMPILED & CHECKED BY: S Simonovic

WEEK ENDING: 23/06/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	1341	30/01/19		N/A	
TOOL BOX	15A	30/01/19	20/06/19	N/A	
SITE BOX	32A	26/11/18		N/A	
PLASTIC TRESTLES	N/A	30/01/19		N/A	
110V EXTENSION LEAD	78A	20/11/18	20/06/19	20/08/19	
110V EXTENSION LEAD	74	20/11/18	20/06/19	20/08/19	
110V EXTENSION LEAD	83	20/11/18		20/08/19	
110V EXTENSION LEAD	471	20/11/18		20/08/19	
110V EXTENSION LEAD	1254	31/01/19		20/08/19	
110V EXTENSION LEAD	1369	05/03/19		20/08/19	
110V SPLITTER BOX	300		20/06/19	20/08/19	
110V SPLITTER BOX	1368	30/01/19		20/08/19	
MAKITA SKILL SAW	705	20/11/18		20/08/19	
BOSCH PISTOL DRILL	889B	20/11/18		20/08/19	
Dust extractor	1363	30/01/19		20/08/19	
DEWALT ½" ROUTER	891A	08/02/19	20/06/19	20/08/19	
MAKITA PLANER	161	08/02/19		20/08/19	
BOSCH JIGSAW	726	08/02/19		20/08/19	
BOSCH HAMMER DRILL	934	05/03/19		20/08/19	
MAKITA ½" ROUTER	PS22	11/02/19	20/06/19	20/08/19	
DEWALT ¼" ROUTER	660	11/02/19		20/08/19	
PASLODE 2 nd fix (ANGLED)	1014	05/03/19		N/A	
THASK LIGHT	1350	05/03/19	20/06/19	20/08/19	
DEWALT CHOPSAW	814	16/04/19		20/08/19	
MAKITA ¼" ROUTER	332	16/04/19		20/08/19	

DUST EXTRACTOR	1241	24/04/19		24/07/19	
MAKITA MULTI TOOL	1380	20/06/19		18/12/19	



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Maggies Marsden

COMPILED & CHECKED BY: J. Godman

WEEK ENDING 23/06/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	1366	15/04/2019		N/A	Condition good
Toolbox	1026	20/05/2019		N/A	Condition good
Toolbox	55A	05/06/2019		N/A	Condition good
A Frame	Big blue one	20/05/2019		N/A	Condition good
110v Lead	158	15/04/2019		24/07/2019	Condition good
110v Lead	1245	15/04/2019		24/07/2019	Condition good
110v Splitter Box	649	15/04/2019		24/07/2019	Condition good
Dust Control Extractor	1242	15/04/2019		24/07/2019	Condition good
Makita Router ¼	1337	15/04/2019		24/07/2019	Condition good
DeWalt Router ¼	782	13/06/19		24/07/2019	Condition good
DeWalt Chopsaw	637	05/06/2019		24/07/2019	Condition good
Makita Jigsaw	1276	05/06/2019		24/07/2019	Condition good
Makita Skillsaw	706	15/04/2018		24/07/2019	Condition good
Makita Planer	751	15/04/2019		24/07/2019	Condition good
Bosch Sds	1330	15/04/2019		24/07/2019	Condition good
Bosch drill	651N	15/04/2019		24/07/2019	Condition good
2 nd Fix Paslode	169	05/06/2019		N/A	Condition good
1 st Fix Paslode	PS 21	21/06/2019		N/A	Condition good
Mobile Tower	RCL3	15/04/2019		N/A	Condition good
Hop – up	980	20/05/2019		N/A	Condition good
Podium Steps	1232	15/04/2019		N/A	Condition good
Hilti Laser	988	20/06/2019		N/A	Condition good

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	Page 1 of 1
				NEXT REVIEW DATE:	07/02/2014	



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: SPS Phase 2

COMPILED & CHECKED BY: J.Wray

WEEK ENDING: 23/06/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOLBOX	456	28/03/19		N/A	
TOOLBOX	41A	16/05/19		N/A	
TOOLBOX	7A	16/05/19		N/A	
TOOLBOX	10A	16/05/19		N/A	
TALL PODIUM STEPS	1231 A	16/05/19		N/A	
TALL PODIUM STEPS	1231 B	16/05/19		N/A	
TALL PODIUM STEPS	PS14	20/05/19		N/A	
TALL PODIUM STEPS	PS30	20/05/19		N/A	
110 V LEAD	1293	16/05/19		15/08/19	
110 V LEAD	1319	16/05/19		15/08/19	
110 V LEAD	1254	16/05/19		15/08/19	
110 V LEAD	1372	16/05/19		01/11/19	
110 V LEAD	1373	16/05/19		01/11/19	
110 V LEAD	1374	16/05/19		01/11/19	
110 V LEAD	1375	16/05/19		01/11/19	
110 V TRANSFORMER	1348	16/05/19		15/08/19	
110 V JUNCTION BOX	246	16/05/19		15/08/19	
110 V JUNCTION BOX	667	16/05/19		15/08/19	
DUST CONTROL EXTRACTOR UNIT	RCL1304	16/05/19		15/08/19	
DUST CONTROL EXTRACTOR UNIT	1214	16/05/19		15/08/19	
BOSCH PISTOL DRILL	972	16/05/19		15/08/19	
MAKITA PISTOL DRILL	1003	16/05/19		15/08/19	
MAKITA SKILLSAW	827	16/05/19		15/08/19	
DEWALT 1/4" ROUTER	1361	16/05/19		15/08/19	
DEWALT 1/4" ROUTER	1357	16/05/19		15/08/19	
BOSCH HAMMER DRILL	941	16/05/19		15/08/19	
MAKITA HAMMER DRILL	1379	22/05/19		???	Needs repair – bit won't stay in chuck
BOSCH HAMMER DRILL	1040	30/05/19		29/08/19	
MAKITA HAMMER DRILL	360	30/05/19		29/08/19	Needs repair – bit won't stay in chuck
MAKITA CHOPSAW	887	16/05/19		15/08/19	
MAKITA CHOPSAW	620	20/05/19		15/08/19	
MAKITA PLANNER	906	16/05/19		15/08/19	
MIKATA JIGSAW	1370	16/05/19		01/11/19	
MIKATA JIGSAW	1371	16/05/19		01/11/19	
A FRAME TROLLEY	???	18/06/19		N/A	
2 nd FIX PASLODE GUN	1295	18/06/19		N/A	
EPSON Workforce WF-7610 PRINTER	WF7610	16/05/19		15/08/19	