

WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Maggies Marsden

COMPILED & CHECKED BY: J. Godman

WEEK ENDING 28/07/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	1366	15/04/2019		N/A	Condition good
Toolbox	1026	20/05/2019		N/A	Condition good
Toolbox	55A	05/06/2019		N/A	Condition good
A Frame	Big blue one	20/05/2019		N/A	Condition good
110v Lead	158	15/04/2019		23/10/2019	Condition good
110v Lead	1245	15/04/2019		23/10/2019	Condition good
110v Lead	471	02/07/2019		23/10/2019	Condition good
110v Lead	13	02/07/2019		23/10/2019	Condition good
110v Splitter Box	649	15/04/2019		23/10/2019	Condition good
110v Splitter Box	648	02/07/2019		23/10/2019	Condition good
Dust Control Extractor	1242	15/04/2019		23/10/2019	Condition good
Dust Control Extractor	1241	05/06/2019		23/10/2019	Condition good
Makita Router ¼	1337	15/04/2019		23/10/2019	Condition good
DeWalt Router ¼	782	13/06/2019		23/10/2019	Condition good
DeWalt Chopsaw	637	05/06/2019		23/10/2019	Condition good
DeWalt Chopsaw	738	02/07/2019		23/10/2019	Condition good
Makita Jigsaw	1276	05/06/2019		23/10/2019	Condition good
Makita Skillsaw	706	15/04/2018		23/10/2019	Condition good
Makita Skillsaw	622	05/06/2019		23/10/2019	Condition good
Makita Planer	751	15/04/2019		23/10/2019	Condition good
Bosch Sds	1330	15/04/2019		23/10/2019	Condition good
Bosch drill	651N	15/04/2019		23/10/2019	Condition good
2 nd Fix Paslode	169	05/06/2019		N/A	Condition good
1 st Fix Paslode	PS 21	21/06/2019		N/A	Condition good
1 st Fix Paslode	920	25/06/2019		N/A	Condition good
Mobile Tower	RCL3	15/04/2019		N/A	Condition good
Hop – up	980	20/05/2019		N/A	Condition good
Podium Steps	1232	15/04/2019		N/A	Condition good



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: WALKERS COURT


COMPILED & CHECKED BY: S Simonovic

WEEK ENDING: 28/07/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	666	13/09/18		N/A	
TOOL BOX	1341	10/07/19		N/A	
110V EXTENSION LEAD	1254	10/07/19		20/08/19	
110V SPLITTER BOX	1368	10/07/19		20/08/19	
MAKITA SKILL SAW	705	10/07/19		20/08/19	
BOSCH PISTOL DRILL	889B	10/07/19		20/08/19	
Dust extractor	1363	10/07/19		20/08/19	
MAKITA PLANER	161	10/07/19		20/08/19	
BOSCH JIGSAW	726	10/07/19		20/08/19	
BOSCH HAMMER DRILL	934	10/07/19		20/08/19	
DEWALT 1/4" ROUTER	660	10/07/19		20/08/19	
DEWALT CHOPSAW	814	10/07/19		20/08/19	
MAKITA MULTI TOOL	1380	10/07/19		18/12/19	

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Wembley W03

COMPILED & CHECKED BY: A. Kulsinskas

WEEK ENDING 28/07/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	1A	05/03/2018		N/A	Condition good
Toolbox	1340	04/05/2018		N/A	Condition good
Toolbox	16A	01/08/2018		N/A	Condition good
Toolbox	29A	01/08/2018		N/A	Condition good
Toolbox	4A	03/09/2018		N/A	Condition good
Toolbox	9A	19/10/2018		N/A	Condition good
110v Lead	211	04/05/2018		25/09/2019	Condition good
110v Lead	1267	04/05/2018		25/09/2019	Condition good
110v Lead	1247	05/03/2018		25/09/2019	Condition good
110v Lead	932	05/03/2018		25/09/2019	Condition good
110v Lead	268	01/08/2018		25/09/2019	Condition good
110v Lead	1356	01/08/2018		25/09/2019	Condition good
110v Lead	104	24/09/2018		25/09/2019	Condition good
110v Splitter Box	265	05/03/2018		25/09/2019	Condition good
110v Splitter Box	2662	19/10/2018		25/09/2019	Condition good
110v Task Light	1360	19/10/2018		25/09/2019	Condition good
Dust Control Extractor	1243	01/08/2018		25/09/2019	Condition good
Dust Control Extractor	1264	21/08/2018		25/09/2019	Condition good
Dust Control Extractor	1353	05/11/2018		25/09/2019	Condition good
Makita Router ½	63	05/03/2018		25/09/2019	Condition good
Makita Router ½	67	05/04/2018		25/09/2019	Condition good
Makita Router ½	1353	04/07/2018		25/09/2019	Condition good
Dewalt Router ½	892	24/09/2018		25/09/2019	Condition good
2 nd Fix Paslode Gun	1336	15/08/2018		N/A	Condition good
2 nd Fix Paslode Gun	1255	17/09/2018		N/A	Condition good
2 nd Fix Paslode Gun	1360	20/09/2018		N/A	Condition good
Makita Chopsaw	940	26/06/2019		26/09/2019	Condition good
Makita Jigsaw	1275	05/03/2018		25/09/2019	Condition good
Makita Skillsaw	1043	04/05/2018		25/09/2019	Condition good
Makita Planer	912	05/03/2018		25/09/2019	Condition good
Bosch Battery Hammer Drill	E1	18/03/2019		N/A	Condition good
Makita Sds	361	04/05/2018		25/09/2019	Condition good
Multi Tool	1280	04/05/2018		25/09/2019	Condition good

DOCUMENT REFERENCE:
DOCUMENT OWNER:

SIT-FM-011
DAS

VERSION NO:


1.1

CREATION DATE:
LAST REVISION DATE:
NEXT REVIEW DATE:

07/02/2013
04/07/2013
07/02/2014

Page 1 of 1

Makita Biscuit cutter	936	05/04/2018		25/09/2019	Condition good
A Frame	1294	24/09/2018		N/A	Condition good
Printer Epson		17/09/2018		25/09/2019	Condition good
Tea Kettle		17/09/2018		25/09/2019	Condition good



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: SPS Phase 2

COMPILED & CHECKED BY: J.Wray

WEEK ENDING: 28/07/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
TOOLBOX	456	28/03/19		N/A	
TOOLBOX	41A	16/05/19		N/A	
TOOLBOX	7A	16/05/19		N/A	
TOOLBOX	10A	16/05/19		N/A	
TALL PODIUM STEPS	1231 A	16/05/19		N/A	
TALL PODIUM STEPS	1231 B	16/05/19		N/A	
TALL PODIUM STEPS	PS14	20/05/19		N/A	
TALL PODIUM STEPS	PS30	20/05/19		N/A	
110 V LEAD	1293	16/05/19		15/08/19	
110 V LEAD	1319	16/05/19		15/08/19	
110 V LEAD	1254	16/05/19		15/08/19	
110 V LEAD	1372	16/05/19		01/11/19	
110 V LEAD	1373	16/05/19		01/11/19	
110 V LEAD	1374	16/05/19		01/11/19	
110 V LEAD	1375	16/05/19		01/11/19	
110 V TRANSFORMER	1348	16/05/19		15/08/19	
110 V JUNCTION BOX	246	16/05/19		15/08/19	
110 V JUNCTION BOX	667	16/05/19		15/08/19	
DUST CONTROL EXTRACTOR UNIT	RCL1304	16/05/19		15/08/19	
DUST CONTROL EXTRACTOR UNIT	1214	16/05/19		15/08/19	
BOSCH PISTOL DRILL	972	16/05/19		15/08/19	
MAKITA PISTOL DRILL	1003	16/05/19		15/08/19	
MAKITA SKILLSAW	827	16/05/19		15/08/19	
DEWALT 1/2" ROUTER	1361	16/05/19		15/08/19	
DEWALT 1/4" ROUTER	1357	16/05/19		15/08/19	
BOSCH HAMMER DRILL	941	16/05/19		15/08/19	
BOSCH HAMMER DRILL	1040	30/05/19		29/08/19	
MAKITA CHOPSAW	887	16/05/19		15/08/19	
DEWALT CHOPSAW	621	01/07/19		03/10/19	
MAKITA PLANNER	906	16/05/19		15/08/19	
MIKATA JIGSAW	1370	16/05/19		01/11/19	
MIKATA JIGSAW	1371	16/05/19		01/11/19	
A FRAME TROLLEY	???	18/06/19		N/A	
2 nd FIX PASLODE GUN	1295	18/06/19		N/A	Rubber tip missing
2 nd FIX PASLODE GUN	72	01/07/19		N/A	Rubber tip missing
ANGLED 2 nd FIX PASLODE GUN	1014	10/07/19		N/A	Rubber tip missing
2 nd FIX PASLODE GUN	991	17/07/19	25/07/19	N/A	Rubber tip missing & not firing pin
EPSON Workforce WF-7610 PRINTER	WF7610	16/05/19		15/08/19	

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	Page 1 of 1
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	