

WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Maggies Marsden


COMPILED & CHECKED BY: J. Godman

WEEK ENDING 04/08/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	1366	15/04/2019		N/A	Condition good
Toolbox	1026	20/05/2019		N/A	Condition good
Toolbox	55A	05/06/2019		N/A	Condition good
A Frame	Big blue one	20/05/2019		N/A	Condition good
110v Lead	158	15/04/2019		23/10/2019	Condition good
110v Lead	1245	15/04/2019		23/10/2019	Condition good
110v Lead	471	02/07/2019		23/10/2019	Condition good
110v Lead	13	02/07/2019		23/10/2019	Condition good
110v Splitter Box	649	15/04/2019		23/10/2019	Condition good
110v Splitter Box	648	02/07/2019		23/10/2019	Condition good
Dust Control Extractor	1242	15/04/2019		23/10/2019	Condition good
Dust Control Extractor	1241	05/06/2019		23/10/2019	Condition good
Makita Router ¼	1337	15/04/2019		23/10/2019	Condition good
DeWalt Router ¼	782	13/06/2019		23/10/2019	Condition good
DeWalt Chopsaw	637	05/06/2019		23/10/2019	Condition good
DeWalt Chopsaw	738	02/07/2019		23/10/2019	Condition good
Makita Jigsaw	1276	05/06/2019		23/10/2019	Condition good
Makita Skillsaw	706	15/04/2018		23/10/2019	Condition good
Makita Skillsaw	622	05/06/2019		23/10/2019	Condition good
Makita Planer	751	15/04/2019		23/10/2019	Condition good
Bosch Sds	1330	15/04/2019		23/10/2019	Condition good
Bosch drill	651N	15/04/2019		23/10/2019	Condition good
2 nd Fix Paslode	169	05/06/2019		N/A	Condition good
1 st Fix Paslode	PS 21	21/06/2019		N/A	Condition good
1 st Fix Paslode	920	25/06/2019		N/A	Condition good
Mobile Tower	RCL3	15/04/2019		N/A	Condition good
Hop – up	980	20/05/2019		N/A	Condition good
Podium Steps	1232	15/04/2019		N/A	Condition good

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	Page 1 of 1
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: WALKERS COURT


COMPILED & CHECKED BY: S Simonovic

WEEK ENDING: 04/08/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	666	13/09/18		N/A	
TOOL BOX	1341	10/07/19		N/A	
110V EXTENSION LEAD	1254	10/07/19		20/08/19	
110V SPLITTER BOX	1368	10/07/19		20/08/19	
MAKITA SKILL SAW	705	10/07/19		20/08/19	
BOSCH PISTOL DRILL	889B	10/07/19		20/08/19	
Dust extractor	1363	10/07/19		20/08/19	
MAKITA PLANER	161	10/07/19		20/08/19	
BOSCH JIGSAW	726	10/07/19		20/08/19	
BOSCH HAMMER DRILL	934	10/07/19		20/08/19	
DEWALT 1/2" ROUTER	660	10/07/19		20/08/19	
DEWALT CHOPSAW	814	10/07/19		20/08/19	
MAKITA MULTI TOOL	1380	10/07/19		18/12/19	

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: SPS Phase 2

COMPILED & CHECKED BY: J.Wray

WEEK ENDING: 04/08/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOLBOX	456	28/03/19		N/A	
TOOLBOX	41A	16/05/19		N/A	
TOOLBOX	7A	16/05/19		N/A	
TOOLBOX	10A	16/05/19		N/A	
TALL PODIUM STEPS	1231 A	16/05/19		N/A	
TALL PODIUM STEPS	1231 B	16/05/19		N/A	
TALL PODIUM STEPS	PS14	20/05/19		N/A	
TALL PODIUM STEPS	PS30	20/05/19		N/A	
110 V LEAD	1293	16/05/19		15/08/19	
110 V LEAD	1319	16/05/19		15/08/19	
110 V LEAD	1254	16/05/19		15/08/19	
110 V LEAD	1372	16/05/19		01/11/19	
110 V LEAD	1373	16/05/19		01/11/19	
110 V LEAD	1374	16/05/19		01/11/19	
110 V LEAD	1375	16/05/19		01/11/19	
110 V TRANSFORMER	1348	16/05/19		15/08/19	
110 V JUNCTION BOX	246	16/05/19		15/08/19	
110 V JUNCTION BOX	667	16/05/19		15/08/19	
DUST CONTROL EXTRACTOR UNIT	RCL1304	16/05/19		15/08/19	
DUST CONTROL EXTRACTOR UNIT	1214	16/05/19		15/08/19	
BOSCH PISTOL DRILL	972	16/05/19		15/08/19	
MAKITA PISTOL DRILL	1003	16/05/19		15/08/19	
MAKITA SKILLSAW	827	16/05/19		15/08/19	
DEWALT 1/4" ROUTER	1361	16/05/19		15/08/19	
DEWALT 1/4" ROUTER	1357	16/05/19		15/08/19	
BOSCH HAMMER DRILL	941	16/05/19		15/08/19	
BOSCH HAMMER DRILL	1040	30/05/19		29/08/19	
MAKITA CHOPSAW	887	16/05/19		15/08/19	
DEWALT CHOPSAW	621	01/07/19		03/10/19	
MAKITA PLANNER	906	16/05/19		15/08/19	
MIKATA JIGSAW	1370	16/05/19		01/11/19	
MIKATA JIGSAW	1371	16/05/19		01/11/19	
A FRAME TROLLEY	???	18/06/19		N/A	
2 nd FIX PASLODE GUN	1295	18/06/19		N/A	Rubber tip missing
2 nd FIX PASLODE GUN	72	01/07/19		N/A	Rubber tip missing
ANGLED 2 nd FIX PASLODE GUN	1014	10/07/19		N/A	Rubber tip missing
EPSON Workforce WF-7610 PRINTER	WF7610	16/05/19		15/08/19	

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	Page 1 of 1
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Wembley W03

COMPILED & CHECKED BY: A. Kulsinskas

WEEK ENDING 04/08/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	1A	05/03/2018		N/A	Condition good
Toolbox	1340	04/05/2018		N/A	Condition good
Toolbox	16A	01/08/2018		N/A	Condition good
Toolbox	29A	01/08/2018		N/A	Condition good
Toolbox	4A	03/09/2018		N/A	Condition good
Toolbox	9A	19/10/2018		N/A	Condition good
110v Lead	211	04/05/2018		25/09/2019	Condition good
110v Lead	1267	04/05/2018		25/09/2019	Condition good
110v Lead	1247	05/03/2018		25/09/2019	Condition good
110v Lead	932	05/03/2018		25/09/2019	Condition good
110v Lead	268	01/08/2018		25/09/2019	Condition good
110v Lead	1356	01/08/2018		25/09/2019	Condition good
110v Lead	104	24/09/2018		25/09/2019	Condition good
110v Splitter Box	265	05/03/2018		25/09/2019	Condition good
110v Splitter Box	2662	19/10/2018		25/09/2019	Condition good
110v Task Light	1360	19/10/2018		25/09/2019	Condition good
Dust Control Extractor	1243	01/08/2018		25/09/2019	Condition good
Dust Control Extractor	1264	21/08/2018		25/09/2019	Condition good
Dust Control Extractor	1353	05/11/2018		25/09/2019	Condition good
Makita Router ¼	63	05/03/2018		25/09/2019	Condition good
Makita Router ½	67	05/04/2018		25/09/2019	Condition good
Makita Router ¼	1353	04/07/2018		25/09/2019	Condition good
Dewalt Router ½	892	24/09/2018		25/09/2019	Condition good
2 nd Fix Paslode Gun	1336	15/08/2018		N/A	Condition good
2 nd Fix Paslode Gun	1255	17/09/2018		N/A	Condition good
2 nd Fix Paslode Gun	1360	20/09/2018		N/A	Condition good
Makita Chopsaw	940	26/06/2019		26/09/2019	Condition good
Makita Jigsaw	1275	05/03/2018		25/09/2019	Condition good
Makita Skillsaw	1043	04/05/2018		25/09/2019	Condition good
Makita Planer	912	05/03/2018		25/09/2019	Condition good
Bosch Battery Hammer Drill	E1	18/03/2019		N/A	Condition good
Makita Sds	361	04/05/2018		25/09/2019	Condition good
Multi Tool	1280	04/05/2018		25/09/2019	Condition good

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------

Makita Biscuit cutter	936	05/04/2018		25/09/2019	Condition good
A Frame	1294	24/09/2018		N/A	Condition good
Printer Epson		17/09/2018		25/09/2019	Condition good
Tea Kettle		17/09/2018		25/09/2019	Condition good