

WEEKLY PLANT RETURN
AND
PLANT SAFETY CHECK


SITE: Maggies Marsden

COMPILED & CHECKED BY: A. Kulsinskas

WEEK ENDING 28/04/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	1366	15/04/2019		N/A	Condition good
110v Lead	158	15/04/2019		24/07/2019	Condition good
110v Lead	1245	15/04/2019		24/07/2019	Condition good
110v Splitter Box	649	15/04/2019		24/07/2019	Condition good
Dust Control Extractor	1242	15/04/2019		24/07/2019	Condition good
Makita Router ¼	1337	15/04/2019		24/07/2019	Condition good
Dewalt Chopsaw	676	15/04/2019		24/07/2019	Condition good
Makita Chopsaw for Metal	956	15/04/2019	25/04/19	24/07/2019	Returned to RCL Office
Bosch Jigsaw	184	15/04/2019	24/07/19		Faulty, Joe collected
Makita Jigsaw	1028	18/04/2019		24/07/2019	Condition good
Makita Skillsaw	706	15/04/2018		24/07/2019	Condition good
Makita Planer	751	15/04/2019		24/07/2019	Condition good
Bosch Sds	1330	15/04/2019		24/07/2019	Condition good
Bosch drill	651N	15/04/2019		24/07/2019	Condition good
Mobile Tower	RCL3	15/04/2019		N/A	Condition good
Podium Steps	1232	15/04/2019		N/A	Condition good



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

**SITE: Wembley Block
W03**

COMPILED & CHECKED BY: J. Godman

WEEK ENDING 28/04/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	1026	05/03/2018		N/A	Condition good
Toolbox	1A	05/03/2018		N/A	Condition good
Toolbox	1340	04/05/2018		N/A	Condition good
Toolbox	16A	01/08/2018		N/A	Condition good
Toolbox	29A	01/08/2018		N/A	Condition good
Toolbox	4A	03/09/2018		N/A	Condition good
Toolbox	9A	19/10/2018		N/A	Condition good
110v Lead	211	04/05/2018		19/06/2019	Condition good
110v Lead	1267	04/05/2018		19/06/2019	Condition good
110v Lead	1247	05/03/2018		19/06/2019	Condition good
110v Lead	932	05/03/2018		19/06/2019	Condition good
110v Lead	268	01/08/2018		19/06/2019	Condition good
110v Lead	1356	01/08/2018		19/06/2019	Condition good
110v Lead	104	24/09/2018		19/06/2019	Condition good
110v Lead	897	24/09/2018		19/06/2019	Condition good
110v Splitter Box	265	05/03/2018		19/06/2019	Condition good
110v Splitter Box	643	04/05/2018		19/06/2019	Condition good
110v Splitter Box	2662	19/10/2018		19/06/2019	Condition good
110v Task Light	1304	04/05/2018		19/06/2019	Condition good
110v Task Light	1360	19/10/2018		19/06/2019	Condition good
Dust Control Extractor	1243	01/08/2018		19/06/2019	Condition good
Dust Control Extractor	1264	21/08/2018		19/06/2019	Condition good
Dust Control Extractor	1353	05/11/2018		19/06/2019	Condition good
Makita Router ¼	63	05/03/2018		19/06/2019	Condition good
Makita Router ½	67	05/04/2018		19/06/2019	Condition good
Makita Router ¼	1353	04/07/2018		19/06/2019	Condition good
Makita Router ¼	959	06/08/2018		19/06/2019	Condition good
Dewalt Router ½	892	24/09/2018		19/06/2019	Condition good
2 nd Fix Paslode Gun	169	04/05/2018		N/A	Condition good
2 nd Fix Paslode Gun	1336	15/08/2018		N/A	Condition good
2 nd Fix Paslode Gun	1255	17/09/2018		N/A	Condition good
2 nd Fix Paslode Gun	1360	20/09/2018		N/A	Condition good
Makita Chopsaw	957	18/09/2018		19/06/2019	Condition good

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------

Makita Jigsaw	1275	05/03/2018		19/06/2019	Condition good
Makita Skillsaw	1043	04/05/2018		19/06/2019	Condition good
Makita Planer	912	05/03/2018		19/06/2019	Condition good
Bosch Battery Hammer Drill	E1	18/03/2019		N/A	Condition good
Makita Sds	361	04/05/2018		19/06/2019	Condition good
Multi Tool	1280	04/05/2018		19/06/2019	Condition good
Makita Biscuit cutter	936	05/04/2018		19/06/2019	Condition good
A Frame		04/05/2018		N/A	Condition good
A Frame	1294	24/09/2018		N/A	Condition good
Printer Epson		17/09/2018		19/06/2019	Condition good
Chain Mortiser	812	18/03/2019		19/06/2019	Condition good
Tea Kettle		17/09/2018		19/06/2019	Condition good



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: WELLINGTON HOUSE

COMPILED & CHECKED BY: S Simonovic

WEEK ENDING: 28/04/19

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	1341	30/01/19		N/A	
TOOL BOX	15A	30/01/19		N/A	
SITE BOX	32A	26/11/18		N/A	
PLASTIC TRESTLES	N/A	30/01/19		N/A	
110V EXTENSION LEAD	78A	20/11/18		13/05/19	
110V EXTENSION LEAD	74	20/11/18		13/05/19	
110V EXTENSION LEAD	83	20/11/18		13/05/19	
110V EXTENSION LEAD	471	20/11/18		13/05/19	
110V EXTENSION LEAD	1254	31/01/19		13/05/19	
110V EXTENSION LEAD	1369	05/03/19		21/06/19	
110V SPLITTER BOX	300			13/05/19	
110V SPLITTER BOX	1368	30/01/19		13/05/19	
MAKITA SKILL SAW	705	20/11/18		13/05/19	
BOSCH PISTOL DRILL	889B	20/11/18		13/05/19	
Dust extractor	1363	30/01/19		13/05/19	
DEWALT ½" ROUTER	891A	08/02/19		13/05/19	
DEWALT CHOPSAW	795	08/02/19	16/04/19	13/05/19	
MAKITA PLANER	161	08/02/19		13/05/19	
BOSCH JIGSAW	726	08/02/19		13/05/19	
BOSCH HAMMER DRILL	934	05/03/19		05/06/19	
MAKITA ½" ROUTER	PS22	11/02/19		13/05/19	
DEWALT ¼" ROUTER	660	11/02/19		13/05/19	
PASLODE 2 nd fix (ANGLED)	1014	05/03/19		N/A	
THASK LIGHT	1350	05/03/19		21/06/19	
DUST EXTRACTOR	?	16/04/19	24/04/19	?	Faulty

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	Page 1 of 1

DEWALT CHOPSAW	814	16/04/19		16/07/19	
MAKITA ¼" ROUTER	332	16/04/19		16/07/19	
DUST EXTRACTOR	1241	24/04/19		24/07/19	