



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: SPS Phase 2

COMPILED & CHECKED BY : J.Wray

WEEK ENDING: 19/01/2020

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOLBOX	1343	22/10/19		N/A	
110 V LEAD	1293	16/05/19		10/04/2020	
110 V LEAD	1372	16/05/19		10/04/2020	
110 V TRANSFORMER	1348	16/05/19		10/04/2020	
110 V JUNCTION BOX	246	16/05/19		10/04/2020	
BOSCH PISTOL DRILL	972	16/05/19		10/04/2020	
MAKITA SKILLSAW	827	16/05/19		10/04/2020	
DEWALT 1/4" ROUTER	1361	16/05/19		10/04/2020	
BOSCH HAMMER DRILL	941	16/05/19		10/04/2020	
DEWALT CHOPSAW	621	01/07/19		10/04/2020	
MAKITA PLANNER	906	16/05/19		10/04/2020	
MIKATA JIGSAW	1371	16/05/19		10/04/2020	
2nd FIX PASLODE GUN	1360	19/08/19		N/A	

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Sebastian st.

COMPILED & CHECKED BY : K.Kulsinskas

WEEK ENDING: 19/01/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	17	09/09/19		N/A	
TO BOX	15a	09/09/19		N/A	
TOOL BOX	11a	09/09/19		N/A	
110V LEAD	0008	09/09/19		05/02/20	
110V LEAD	0009	09/09/19		05/02/20	
110V LEAD	0010	09/09/19		05/02/20	
110V LEAD	83	09/09/19		05/02/20	
110V LEAD	78	09/09/19		05/02/20	
110 V SPLITTER BOX	1227	09/09/19		05/02/20	
Bosh jigsaw	1256	09/09/19		05/02/20	
Bosh hammer drill	1329	09/09/19		05/02/20	
Makita router 1/4	959	09/09/19		05/02/20	
Makita skilsaw	20984	09/09/19		05/02/20	
Makita planer	201	09/09/19		05/02/20	
Makita chopsaw	785	09/09/19	17-01-20	05/02/20	
Dewalt router 1/4	1026	09/09/19		05/02/20	
Hoover	1343	09/09/19		05/02/20	
A-Frame trolley	239	19/09/19		N/A	
Paslode gun 2fix	529	07-11-19		N/A	
Hoover	1265	07-11-19	17-01-20	05/02/20	Not working
Hoover	1303	07-11-19		05/02/20	
Splitter box	667	09-12-19		05/02/20	
Splitter box	28	09-12-19		05/02/20	

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------

Task light	1304	09-12-19		05/02/20	
Task light	234	09-12-19		05/02/20	
A-Frame troplley	?	09-12-19			No number
Festool plunge saw	1385	09-01-20		06-07-20	
Makita planer	751	09-12-19		05/02/20	
Spliter box	243	09-12-19		05/02/20	
Dewalt chop saw	785	17-01-20		17-06-20	
Dewalt chop saw	786	17-01-20		17-06-20	

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	Page 2 of 1



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

**SITE: PLUMSTEAD
LIBRARY**

COMPILED & CHECKED BY: A. Kulsinskas

WEEK ENDING 19/01/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Printer Epson		21/10/2019		22/01/2020	Good
Toolbox	1341	21/10/2019		N/A	Good
Toolbox	1340	26/11/2019		N/A	Good
Toolbox	No ID	26/11/2019		N/A	Good
Toolbox	No ID	26/11/2019		N/A	Good
Toolbox	1366	21/10/2019		N/A	Good
110v Extension Lead	1254	21/10/2019		22/01/2020	Good
110v Extension Lead	78	03/12/2019		04/02/20	Good
110v Extension Lead	471	03/12/2019		04/02/20	Good
110V Splitter box	1368	21/10/2019		22/01/2020	Good
110V Splitter box	1230	03/12/2019		04/02/20	Good
110V Splitter box	963	03/12/2019		04/02/20	Good
Makita Skill Saw	705	21/10/2019		22/01/2020	Good
Bosch Pistol Drill	889B	21/10/2019		22/01/2020	Good
Dust Extractor	1363	21/10/2019		22/01/2020	Good
Dust Extractor	1214	12/11/2019		13/05/2020	Good
Dust Extractor	1359	03/12/2019		04/02/20	Good
Makita Planer	161	21/10/2019		22/01/2020	Good
Bosch Jigsaw	726	21/10/2019		22/01/2020	Good
Bosch Hammer Drill	934	21/10/2019		22/01/2020	Good
DeWalt ¼ Router	660	21/10/2019		22/01/2020	Good
Makita ¼ Router	63	03/12/19		04/02/20	Good
Makita ¼ Router	1337	03/12/19		04/02/20	Good
DeWalt Chop Saw	814	21/10/2019		22/01/2020	Good
DeWalt Chop Saw	637	03/12/19		04/02/20	Good
Makita Multitool	1380	21/10/2019		22/01/2020	Good
Makita Sander	992	03/12/19		04/02/20	Good
Morticer	812	03/12/19		04/02/20	Good
Podium Steps	PS-27	30/10/19		N/A	Good
Podium Steps	PS-30	30/10/19		N/A	Good
Podium Steps	101	26/11/19		N/A	Good
A Frame	1294	03/12/19		N/A	Good
Task Light	33	30/10/19		22/01/2020	Good

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------

Task Light	937	30/10/19		22/01/2020	Good
Task Light	1351	12/11/19		09/01/2020	Not in use
Task Light	1350	12/11/19		09/01/2020	Not in use
Mobile Tower	5	27/11/19		N/A	Good
2 nd fix Paslode Gun	1382	18/12/19		N/A	Good
2 nd fix Paslode Gun	1384	13/12/19		N/A	New

WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: NEW END

COMPILED & CHECKED BY: G.Buck

WEEK ENDING: 19-01-2020

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

[illegible]