



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: SPS Phase 2

COMPILED & CHECKED BY: J.Wray

WEEK ENDING: 01/03/2020

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u> | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u> |
|---------------------|-----------------|---------------------|----------------------|-------------------------|---|
| TOOLBOX | 1343 | 22/10/19 | 25/02/20 | N/A | |
| 110 V LEAD | 1293 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| 110 V LEAD | 1372 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| 110 V TRANSFORMER | 1348 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| 110 V JUNCTION BOX | 246 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| BOSCH PISTOL DRILL | 972 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| MAKITA SKILLSAW | 827 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| DEWALT 1/4" ROUTER | 1361 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| BOSCH HAMMER DRILL | 941 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| DEWALT CHOPSAW | 621 | 01/07/19 | 25/02/20 | 10/04/2020 | |
| MAKITA PLANNER | 906 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| MIKATA JIGSAW | 1371 | 16/05/19 | 25/02/20 | 10/04/2020 | |
| 2nd FIX PASLODE GUN | 1360 | 19/08/19 | 25/02/20 | N/A | |
| SMALL PODIUM STEPS | RCL 101 | 20/02/20 | 25/02/20 | N/A | |
| SMALL PODIUM STEPS | SW03 | 20/02/20 | 25/02/20 | N/A | |
| NEW TOOLBOX | ??? | | 25/02/20 | N/A | Needs new locks and plates welded on and painting |
| NEW TOOLBOX | ??? | | 25/02/20 | N/A | Needs new locks and plates welded on and painting |

| | | | | | | |
|--|-------------------|-------------|-----|--|--|-------------|
| DOCUMENT REFERENCE: DOCUMENT OWNER: | SIT-FM-011 DAS | VERSION NO: | 1.1 | CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE: | 07/02/2013 04/07/2013 07/02/2014 | Page 1 of 1 |
|--|-------------------|-------------|-----|--|--|-------------|

WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: NEW BOND STREET

WEEK ENDING:

Start Site 01/03/20

COMPILED & CHECKED BY: M. Robinson

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

[illegible]



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Sebastian st.

COMPILED & CHECKED BY: K.Kulsinskas

WEEK ENDING: 01/03/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u> | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u> |
|--------------------|-----------------|-------------------------|--------------------------|-----------------------------|---|
| TOOL BOX | 17 | 09/09/19 | | N/A | |
| TOOL BOX | 15a | 09/09/19 | | N/A | |
| TOOL BOX | 11a | 09/09/19 | | N/A | |
| 110V LEAD | 0008 | 09/09/19 | | 10/05/20 | |
| 110V LEAD | 0009 | 09/09/19 | | 10/05/20 | |
| 110V LEAD | 0010 | 09/09/19 | | 10/05/20 | |
| 110V LEAD | 83 | 09/09/19 | | 10/05/20 | |
| 110V LEAD | 78 | 09/09/19 | | 10/05/20 | |
| 110 V SPLITTER BOX | 1227 | 09/09/19 | | 10/05/20 | |
| Bosh jigsaw | 1256 | 09/09/19 | | 10/05/20 | |
| Bosh hammer drill | 1329 | 09/09/19 | | 10/05/20 | |
| Makita router 1/4 | 959 | 09/09/19 | | 10/05/20 | |
| Makita skilsaw | 20984 | 09/09/19 | | 10/05/20 | |
| Makita planer | 201 | 09/09/19 | | 10/05/20 | |
| Dewalt router 1/4 | 1026 | 09/09/19 | | 10/05/20 | |
| Hoover | 1343 | 09/09/19 | | 10/05/20 | |
| A-Frame trolley | 239 | 19/09/19 | | N/A | |
| Paslode gun 2fix | 529 | 07-11-19 | | N/A | |
| Hoover | 1303 | 07-11-19 | | 10/05/20 | |
| Splitter box | 667 | 09-12-19 | | 10/05/20 | |
| Splitter box | 28 | 09-12-19 | | 10/05/20 | |
| Task light | 1304 | 09-12-19 | | 10/05/20 | |
| Task light | 234 | 09-12-19 | | 10/05/20 | |

| | | | | | |
|--------------------|------|----------|--|----------|--|
| A-Frame troplley | 120 | 09-12-19 | | N/A | |
| Festool plunge saw | 1385 | 09-01-20 | | 06-07-20 | |
| Makita planer | 751 | 09-12-19 | | 10/05/20 | |
| Splitter box | 243 | 09-12-19 | | 10/05/20 | |
| Dewalt chop saw | 785 | 17-01-20 | | 17-06-20 | |
| Dewalt chop saw | 786 | 17-01-20 | | 17-06-20 | |
| Hoover | 1214 | 07-02-20 | | 10/05/20 | |
| Hoover | 1363 | 07-02-20 | | 10/05/20 | |
| Skill saw | 705 | 07-02-20 | | 10/05/20 | |
| Chopsaw | 814 | 07-02-20 | | 10/05/20 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: NEW END

COMPILED & CHECKED BY: G.Buck

WEEK ENDING: 01-03-2020

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u> | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u> |
|--------------------|-----------------|---------------------|----------------------|-------------------------|---|
| CHOPSAW | 676 | 23-09-19 | 18-10-19 | | |
| EXTRACTOR / HOOVER | 1213 | 23-09-19 | | 10-04-20 | |
| SPLITTER BOX | 643 | 23-09-19 | | 10-04-20 | |
| DEWALT ROUTER | 1367 | 23-09-19 | | 10-04-20 | |
| HAMMER DRILL | 22 | 23-09-19 | | 10-04-20 | |
| MAKITA | 913 | 23-09-19 | | 10-04-20 | |
| SKILL SAW | 918 | 23-09-19 | | 10-04-20 | |
| JIGSAW | 666 | 23-09-19 | 23-01-20 | 10-04-20 | |
| ROUTER | 1208 | 23-09-19 | | 10-04-20 | |
| LEAD | 0007 | 23-09-19 | | 10-04-20 | |
| LEAD | 0006 | 23-09-19 | | 10-04-20 | |
| LEAD | 930 | 23-09-19 | | 10-04-20 | |
| LEAD | 211 | 23-09-19 | | 10-04-20 | |
| LEAD | 74 | 23-09-19 | | 10-04-20 | |
| TOOL BOX | 29A | 23-09-19 | | | |
| TOOL BOX | 4A | 23-09-19 | | | |
| TOOL BOX | 48 | 23-09-19 | | | |
| DEWALT ROUTER | 1367 | 30-09-19 | | 10-04-20 | |
| CHOPSAW | 334 | 15-01-20 | | 10-04-20 | |
| TOOLBOX | | 15-01-20 | | | |
| TOOLBOX | | 15-01-20 | | | |
| TOOLBOX | 48 | 15-01-20 | | | |
| JIGSAW | R195 | 23-01-20 | | 21-04-20 | |
| TASK LIGHT | 29 | 23-01-20 | | 21-04-20 | |
| TASK LIGHT | 1307 | 23-01-20 | | 21-04-20 | |
| TASK LIGHT | 1308 | 23-01-20 | | 21-04-20 | |
| LEAD | 268 | 23-01-20 | | 21-04-20 | |
| LEAD | 215 | 23-01-20 | | 21-04-20 | |
| FLIPOVER SAW | 298 | 23-01-20 | | 21-04-20 | |
| PLANER | 619 | 23-01-20 | | 21-04-20 | |
| EXTRACTOR / HOOVER | 1353 | 23-01-20 | | 10-04-20 | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| | | | | | | |
|--|-------------------|-------------|-----|--|--|-------------|
| DOCUMENT REFERENCE: DOCUMENT OWNER: | SIT-FM-011 DAS | VERSION NO: | 1.1 | CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE: | 07/02/2013 04/07/2013 07/02/2014 | Page 1 of 2 |
|--|-------------------|-------------|-----|--|--|-------------|



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: PLUMSTEAD
LIBRARY

COMPILED & CHECKED BY: A. Kulsinskas

WEEK ENDING 01/03/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u> | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u> |
|---------------------------------|-----------------|---------------------|----------------------|-------------------------|---|
| Printer Epson | | 21/10/2019 | | 22/04/2020 | Good |
| Toolbox | 1341 | 21/10/2019 | | N/A | Good |
| 110v Extension Lead | 1254 | 21/10/2019 | | 22/04/2020 | Good |
| 110V Splitter box | 1230 | 03/12/2019 | | 22/04/2020 | Good |
| 110V Splitter box | 963 | 03/12/2019 | | 22/04/2020 | Good |
| Small Makita Skill Saw | 1043 | 13.02.20 | 07.02.20 | 22/04/2020 | Good |
| Dust Extractor | 1359 | 03/12/2019 | | 22/04/2020 | Good |
| Makita Planer | 161 | 21/10/2019 | | 22/04/2020 | Good |
| Bosch Jigsaw | 726 | 21/10/2019 | | 22/04/2020 | Good |
| Bosch Hammer Drill | 934 | 21/10/2019 | | 22/04/2020 | Good |
| Makita ¼ Router | 63 | 03/12/19 | | 22/04/2020 | Good |
| DeWalt Chop Saw | 637 | 03/12/19 | | 22/04/2020 | Good |
| Makita Multitool | 1380 | 21/10/2019 | | 22/04/2020 | Good |
| Morticer | 812 | 03/12/19 | | 22/04/2020 | Good |
| 2 nd fix Paslode Gun | 1384 | 13/12/19 | 26.02.20 | N/A | Sent to Woking Site |
| | | | | | |

WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: KNIGHTSBRIDGE

COMPILED & CHECKED BY: G.Buck

WEEK ENDING: 01-03-2020

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

[illegible]