



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Hilton
Hotel Woking

COMPILED & CHECKED BY:

J. Wray / J. Godman

WEEK ENDING 02/08/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	7A	20/02/2020		N/A	Good Condition
Toolbox	14A	02/03/2020		N/A	Good Condition
Toolbox	1A	02/03/2020		N/A	Good Condition
Toolbox	16A	02/03/2020		N/A	Good Condition
Toolbox	23A	12/06/2020		N/A	Good Condition
Toolbox	25A	12/06/2020		N/A	Good Condition
Toolbox	17	15/07/2020		N/A	Good Condition
Toolbox	8A	15/07/2020		N/A	Good Condition
Toolbox (small)	1026	22/06/2020		N/A	Good Condition
2 nd Fix Paslode Gun	1384	02/03/2020		N/A	Good Condition
Tripod Light	1350	02/03/2020		15/08/2020	Only one light working
Task Light	1306	02/03/2020		15/08/2020	Good Condition
Task Light	34	02/03/2020		14/10/2020	Good Condition
A Frame	Big Green	20/02/2020		N/A	Good Condition
A Frame	Big Blue	04/06/2020		N/A	Good Condition
110v Lead	13	20/02/2020		15/08/2020	Good Condition
110v Lead	1247	20/02/2020		15/08/2020	Good Condition
110v Lead	1263	20/02/2020		15/08/2020	Good Condition
110v Lead	1266	20/02/2020		15/08/2020	Good Condition
110v Lead	1253	20/02/2020		15/08/2020	Good Condition
110v Splitter Box	1241	20/02/2020		15/08/2020	Good Condition
110v Splitter Box	649	12/06/2020		08/09/2020	Good Condition
Dust Control Extractor	1363	12/06/2020		01/11/2020	Good Condition
Dust Control Extractor	1242	20/02/2020		15/08/2020	Good Condition
Dust Control Extractor	1264	15/07/2020		04/09/2020	Good Condition
DeWalt Router ¼	660	20/02/2020		15/08/2020	Missing Depth Gauge
Makita Router ½	67	20/02/2020		15/08/2020	Good Condition
Dewalt Chop saw	621	19/06/2020		16/09/2020	Good Condition
Makita Jigsaw	1276	20/02/2020		15/08/2020	Good Condition
Makita Skill saw	622	20/02/2020		15/08/2020	Good Condition
Makita Planer	942	20/02/2020		15/08/2020	Good Condition
Bosch SDS	894	20/02/2020		15/08/2020	Good Condition

SUB CONTRACTORS POWER TOOLS					
<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Bosch Chopsaw	F&S1	10/06/2020		18/10/2020	Good Condition
Makita ¼" Router	F&S2	10/06/2020		18/10/2020	Good Condition
Dewalt ½" Router	F&S3	10/06/2020		18/10/2020	Good Condition
Dewalt Chopsaw	IH1	20/07/2020		18/10/2020	Good Condition
Dewalt ½" Router	IH2	20/07/2020		18/10/2020	Good Condition

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 2 of 1
--	-------------------	-------------	-----	--	--	-------------

WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Sebastian st.

COMPILED & CHECKED BY : D Sanders

WEEK ENDING: 02/08/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	15a	09/09/19	27-07-20	N/A	
110V LEAD	0008	09/09/19	27-07-20	01/11/20	
110V LEAD	0009	09/09/19	27-07-20	01/11/20	
110V LEAD	78	09/09/19	27-07-20	01/11/20	
110 V SPLITTER BOX	1227	09/09/19	27-07-20	01/11/20	
Bosh jigsaw	1256	09/09/19		01/11/20	
Bosh hammer drill	1329	09/09/19		01/11/20	
Makita router 1/4	959	09/09/19		01/11/20	
Makita planer	201	09/09/19		01/11/20	
Dewalt router 1/4	1026	09/09/19	27-07-20	01/11/20	
Toolbox	15	09/09/19		N/A	
Toolbox	21	09/09/19		N/A	
Hoover	1343	09/09/19		01/11/20	
Paslode gun 2fix	529	07-11-19		N/A	
Task light	1304	09-12-19	27-07-20	01/11/20	
Festool plunge saw	1385	09-01-20		01/11/20	
Makita planer	751	09-12-19	27-07-20	01/11/20	
Splitter box	246	09-12-19	27-07-20	01/11/20	
Hoover	1214	07-02-20	27-07-20	01/11/20	
Hoover	1303	07-02-20	27-07-20	01/11/20	
Chopsaw	814	07-02-20		01/11/20	
Infrared thermometer	13876	20-04-20		N/A	