



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: Hilton
Hotel Woking

COMPILED & CHECKED BY:

J. Wray / J. Godman

WEEK ENDING 30/08/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	7A	20/02/2020		N/A	Good Condition
Toolbox	14A	02/03/2020		N/A	Good Condition
Toolbox	1A	02/03/2020		N/A	Good Condition
Toolbox	16A	02/03/2020		N/A	Good Condition
Toolbox	23A	12/06/2020		N/A	Good Condition
Toolbox	25A	12/06/2020		N/A	Good Condition
Toolbox	17	15/07/2020		N/A	Good Condition
Toolbox	8A	15/07/2020		N/A	Good Condition
Toolbox (small)	1026	22/06/2020		N/A	Good Condition
Hop Up	1024	25/08/2020		N/A	Good Condition
2 nd Fix Paslode Gun	1384	02/03/2020		N/A	Good Condition
Tripod Light	1350	02/03/2020		20/11/2020	Only one light working
Task Light	1306	02/03/2020		20/11/2020	Good Condition
Task Light	34	02/03/2020		20/11/2020	Good Condition
A Frame	Big Green	20/02/2020		N/A	Good Condition
A Frame	Big Blue	04/06/2020		N/A	Good Condition
110v Lead	13	20/02/2020		20/11/2020	Good Condition
110v Lead	1247	20/02/2020		20/11/2020	Good Condition
110v Lead	1263	20/02/2020		20/11/2020	Good Condition
110v Lead	1266	20/02/2020		20/11/2020	Good Condition
110v Lead	1253	20/02/2020		20/11/2020	Good Condition
110v Splitter Box	1241	20/02/2020		20/11/2020	Good Condition
110v Splitter Box	649	12/06/2020		20/11/2020	Good Condition
Dust Control Extractor	1363	12/06/2020		20/11/2020	Good Condition
Dust Control Extractor	1242	20/02/2020		20/11/2020	Good Condition
Dust Control Extractor	1264	15/07/2020		20/11/2020	Good Condition
DeWalt Router ¼	660	20/02/2020		20/11/2020	Missing Depth Gauge
Makita Router ½	67	20/02/2020		20/11/2020	Good Condition
DeWalt Router ¼	1361	25/08/2020		27/11/2020	Good Condition
DeWalt Chop saw	621	19/06/2020		20/11/2020	Good Condition
Makita Jigsaw	1276	20/02/2020		20/11/2020	Good Condition
Makita Skill saw	622	20/02/2020		20/11/2020	Good Condition
Makita Planer	942	20/02/2020		20/11/2020	Good Condition
Bosch SDS	894	20/02/2020		20/11/2020	Good Condition

SUB CONTRACTORS POWER TOOLS					
<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Bosch Chopsaw	F&S1	10/06/2020	07/08/2020	18/10/2020	Good Condition
Makita ¼" Router	F&S2	10/06/2020	07/08/2020	18/10/2020	Good Condition
Dewalt ½" Router	F&S3	10/06/2020	07/08/2020	18/10/2020	Good Condition


DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	Page 2 of 1
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	

AND
PLANT SAFETY CHECK

COMPILED & CHECKED BY : D Sanders

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

[illegible]



SITE: Knightsbridge

COMPILED & CHECKED BY: G.Buck

WEEK ENDING 30/08/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------