

AND
PLANT SAFETY CHECK

COMPILED & CHECKED BY : D Sanders

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Hilton
Hotel Woking

COMPILED & CHECKED BY:

J. Wray / J. Godman

WEEK ENDING 27/09/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Toolbox	7A	20/02/2020		N/A	Good Condition
Toolbox	14A	02/03/2020		N/A	Good Condition
Toolbox	1A	02/03/2020		N/A	Good Condition
Toolbox	16A	02/03/2020		N/A	Good Condition
Toolbox	23A	12/06/2020		N/A	Good Condition
Toolbox	25A	12/06/2020		N/A	Good Condition
Toolbox	17	15/07/2020		N/A	Good Condition
Toolbox	8A	15/07/2020		N/A	Good Condition
Toolbox (small)	1026	22/06/2020		N/A	Good Condition
Hop Up	1024	25/08/2020		N/A	Good Condition
2 nd Fix Paslode Gun	1384	02/03/2020		N/A	Good Condition
Tripod Light	1350	02/03/2020		20/11/2020	Only one light working
Task Light	1306	02/03/2020		20/11/2020	Good Condition
Task Light	34	02/03/2020		20/11/2020	Good Condition
A Frame	Big Green	20/02/2020		N/A	Good Condition
A Frame	Big Blue	04/06/2020		N/A	Good Condition
110v Lead	13	20/02/2020		20/11/2020	Good Condition
110v Lead	1247	20/02/2020		20/11/2020	Good Condition
110v Lead	1263	20/02/2020		20/11/2020	Good Condition
110v Lead	1266	20/02/2020		20/11/2020	Good Condition
110v Lead	1253	20/02/2020		20/11/2020	Good Condition
110v Splitter Box	1241	20/02/2020		20/11/2020	Good Condition
110v Splitter Box	649	12/06/2020		20/11/2020	Good Condition
Dust Control Extractor	1363	12/06/2020		20/11/2020	Good Condition
Dust Control Extractor	1242	20/02/2020		20/11/2020	Good Condition
Dust Control Extractor	1264	15/07/2020		20/11/2020	Good Condition
DeWalt Router ¼	660	20/02/2020		20/11/2020	Missing Depth Gauge
Makita Router ¼	67	20/02/2020		20/11/2020	Good Condition
DeWalt Router ¼	1361	25/08/2020		27/11/2020	Good Condition
DeWalt Chop saw	621	19/06/2020		20/11/2020	Good Condition
Makita Jigsaw	1276	20/02/2020		20/11/2020	Good Condition
Makita Skill saw	622	20/02/2020		20/11/2020	Good Condition
Makita Planer	942	20/02/2020		20/11/2020	Good Condition
Bosch SDS	894	20/02/2020		20/11/2020	Good Condition
SUB CONTRACTORS POWER TOOLS					
Makita Chop saw	MTR PG-01	14/09/2020		25/12/2020	Good Condition
DeWalt Router ¼	706966	14/09/2020		25/12/2020	Good Condition
Festool Router ¼	OF 1010 EQ	14/09/2020		25/12/2020	Good Condition



WEEKLY PLANT RETURN
AND
PLANT SAFETY CHECK

SITE: Knightsbridge

COMPILED & CHECKED BY: G.Buck

WEEK ENDING 27/09/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
CHOPSAW	676	25-02-20		13-11-20	
EXTRACTOR / HOOVER	1304	25-02-20		13-11-20	
SPLITTER BOX	1368	25-02-20		13-11-20	
DEWALT ROUTER	1357	25-02-20		13-11-20	
HAMMER DRILL	1040	25-02-20		13-11-20	
MAKITA PISTOL DRILL	1003	25-02-20		13-11-20	
SKILL SAW	706	25-02-20		13-11-20	
MAKITA SKILL SAW	1043	05-07-20		13-11-20	
JIGSAW	48	25-02-20		13-11-20	
LEAD	1316	25-02-20		13-11-20	
LEAD	930	25-02-20		29-08-20	
LEAD	1254	25-02-20		13-11-20	
LEAD	897	25-02-20		13-11-20	
TOOLBOX	RCL3A	25-02-20		N/A	
TOOLBOX	RCL1340	25-02-20		N/A	
TOOLBOX	1342	15-05-20		N/A	
TOOLBOX	41A	15-05-20		N/A	
PODIUM STEPS	-	25-02-20		N/A	
A FRAME	Yellow	25-02-20		N/A	
2 ND FIX PASLODE GUN	1360	15-06-20		N/A	
2 ND FIX AIRGUN	1131	15-06-20		N/A	
AIR COMPRESOR	1383	15-06-20		13-11-20	
PRINTER EPSON	W17610	05-05-20		13-11-20	



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: NEW END

COMPILED & CHECKED BY: P HAUGH

WEEK ENDING: 20-09-2020

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
EXTRACTOR / HOOVER	1213	23-09-19	10/08	27-08-20	ALL PAT TESTED 29/05
SPLITTER BOX	643	23-09-19		27-08-20	
DEWALT ROUTER	1367	23-09-19		27-08-20	
HAMMER DRILL	22	23-09-19		27-08-20	
MAKITA	913	23-09-19		27-08-20	
SKILL SAW	918	23-09-19		27-08-20	
ROUTER	1208	23-09-19	08/09	27-08-20	
LEAD	0007	23-09-19	08/09	27-08-20	
LEAD	0006	23-09-19	08/09	27-08-20	
LEAD	930	23-09-19	08/09	27-08-20	
LEAD	211	23-09-19		27-08-20	
LEAD	74	23-09-19		27-08-20	
TOOL BOX	29A	23-09-19		NA	
TOOL BOX	4A	23-09-19	17/07	NA	
TOOL BOX	48	23-09-19	08/09	NA	
EXTRACTOR	1367	30-09-20		27-08-20	
CHOPSAW	334	15-01-20	10/08	27-08-20	
TOOLBOX	28	15-01-20	08/09	NA	
TOOLBOX	-	15-01-20	17/07	NA	
TOOLBOX	-	15-01-20		NA	
JIGSAW	184	23-01-20		27-08-20	
TASK LIGHT	29	23-01-20	10/08	27-08-20	
TASK LIGHT	1307	23-01-20	10/08	27-08-20	
TASK LIGHT	1308	23-01-20	10/08	27-08-20	
LEAD	268	23-01-20		27-08-20	
LEAD	215	23-01-20		27-08-20	
PLANER	619	23-01-20	10/08	27-08-20	
MAKITA CHOP SAW	785	??		27-08-20	
PLANNER	731	??		27-08-20	
PASSLODE	1336	??		NA	
PASSLODE	1295	??		NA	



WEEKLY PLANT RETURN

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO: 1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 2
--	-------------------	--------------------	--	--	-------------