



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: VSW

COMPILED & CHECKED BY: J.Godman

WEEK ENDING 27/12/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
Toolbox	7A ✓	20/02/2020		N/A	Good Condition
Toolbox	14A ✓	02/03/2020		N/A	Good Condition
Toolbox	1A ✓	02/03/2020		N/A	Good Condition
Toolbox	16A ✓	02/03/2020		N/A	Good Condition
Toolbox	23A ✓	12/06/2020		N/A	Good Condition
Toolbox	25A ✓	12/06/2020		N/A	Good Condition
Toolbox	17 ✓	15/07/2020		N/A	Good Condition
Toolbox	8A ✓	15/07/2020		N/A	Good Condition
Toolbox (small)	1026 ✓	22/06/2020		N/A	Good Condition
Hop Up	1024 ✓	25/08/2020		N/A	Good Condition
Hop Up	980 ✓	20/11/2020		N/A	Good Condition
Hop Up	1035 ✓	20/11/2020		N/A	Good Condition
2 nd Fix Paslode Gun	1382 ✓	07/10/2020		N/A	Good Condition
2 nd Fix Paslode Gun	991 ✓	30/09/2020		N/A	Good Condition
Task Light	1306 ✓	02/03/2020		15/03/2021	Good Condition
Task Light	34 ✓	02/03/2020		15/03/2021	Good Condition
Task Light	33 ✓	14/10/2020		15/03/2021	Good Condition
Task Light	31 ✓	14/10/2020		15/03/2021	Good Condition
A Frame	Big Green -	20/02/2020		N/A	Good Condition
A Frame	Big Blue -	04/06/2020		N/A	MISSING / STOLEN
110v Lead	13 ✓	20/02/2020		15/03/2021	Good Condition
110v Lead	1247 ✓	20/02/2020		15/03/2021	Good Condition
110v Lead	1263 -	20/02/2020		15/03/2021	Good Condition
110v Lead	1266 ✓	20/02/2020		15/03/2021	Good Condition
110v Lead	1253 ✓	20/02/2020		15/03/2021	Good Condition
110v Lead	1394 ✓	20/10/2020		15/03/2021	Good Condition
110v Lead	1395 ✓	20/10/2020		15/03/2021	Good Condition
110v Lead	1396 ✓	20/10/2020		15/03/2021	Good Condition
110v Splitter Box	1241 ✓	20/02/2020		15/03/2021	Good Condition
110v Splitter Box	649 ✓	12/06/2020		15/03/2021	Good Condition
110v Splitter Box	246 ✓	05/10/2020		15/03/2021	Good Condition
Dust Control Extractor	1363 ✓	12/06/2020		15/03/2021	Good Condition
Dust Control Extractor	1353 -	13/10/2020		15/03/2021	Good Condition
Dust Control Extractor	1264 ✓	15/07/2020		15/03/2021	Good Condition
Dust Control Extractor	1214 ✓	05/10/2020		15/03/2021	Good Condition
Dust Control Extractor	1343 -	20/10/2020		15/03/2021	Good Condition
DeWalt Router ¼	660 ✓	20/02/2020		15/03/2021	Missing Depth Gauge

DOCUMENT REFERENCE:
DOCUMENT OWNER:

SIT-FM-011
DAS

VERSION NO:

1.1

CREATION DATE:
LAST REVISION DATE:
NEXT REVIEW DATE:

07/02/2013
04/07/2013
07/02/2014

Page 1 of 1

Makita Router ½	67 ✓	20/02/2020		15/03/2021	Good Condition
Makita Router ¼	1208 ✓	05/10/2020		15/03/2021	Good Condition
DeWalt Router ¼	1361 ✓	25/08/2020		15/03/2021	Good Condition
DeWalt Chop saw	621 ✓	19/06/2020		15/03/2021	Good Condition
DeWalt Chop saw	786 ✓	05/10/2020		15/03/2021	Good Condition
Makita Jigsaw	1276 ✓	20/02/2020		15/03/2021	Good Condition
Makita Jigsaw	1370 ✓	20/10/2020		15/03/2021	Good Condition
Makita Skill saw	622 ✓	20/02/2020		15/03/2021	Good Condition
Festool saw	1385 ✓	07/10/2020		15/03/2021	Good Condition
Festool Guide	R1 ✓	07/10/2020		N/A	Good Condition
Festool Guide	R2 ✓	07/10/2020		N/A	Good Condition
Makita Planer	942 ✓	20/02/2020		15/03/2021	Good Condition
Makita Planer	161 ✓	05/10/2020		15/03/2021	Good Condition
Bosch Hammer Drill	894 ✓	20/02/2020		15/03/2021	Good Condition
Makita Hammer Drill	361 ✓	20/10/2020		15/03/2021	Good Condition
Makita Multi Tool	1280 ✓	07/10/2020		15/03/2021	Good Condition