

N/

WEEKLY PLANT RETURN**AND****PLANT SAFETY CHECK****SITE: Sebastian st.****COMPILED & CHECKED BY : K.Kulsinskas****WEEK ENDING: 26/04/20**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	17	09/09/19		N/A	
TOOL BOX	15a	09/09/19		N/A	
TOOL BOX	11a	09/09/19		N/A	
110V LEAD	0008	09/09/19		10/05/20	
110V LEAD	0009	09/09/19		10/05/20	
110V LEAD	0010	09/09/19		10/05/20	
110V LEAD	83	09/09/19		10/05/20	
110V LEAD	78	09/09/19		10/05/20	
110 V SPLITTER BOX	1227	09/09/19		10/05/20	
Bosh jigsaw	1256	09/09/19		10/05/20	
Bosh hammer drill	1329	09/09/19		10/05/20	
Makita router 1/4	959	09/09/19		10/05/20	
Makita skilsaw	20984	09/09/19		10/05/20	
Makita planer	201	09/09/19		10/05/20	
Dewalt router 1/4	1026	09/09/19		10/05/20	
Hoover	1343	09/09/19		10/05/20	
A-Frame trolley	239	19/09/19		N/A	
Paslode gun 2fix	529	07-11-19		N/A	
Hoover	1303	07-11-19		10/05/20	
Splitter box	667	09-12-19		10/05/20	
Splitter box	28	09-12-19		10/05/20	
Task light	1304	09-12-19		10/05/20	
Task light	234	09-12-19		10/05/20	

DOCUMENT REFERENCE:
DOCUMENT OWNER:

SIT-FM-011
DAS

VERSION NO:

1.1

CREATION DATE:
LAST REVISION DATE:
NEXT REVIEW DATE:

07/02/2013
04/07/2013
07/02/2014

Page 1 of 1

A-Frame troplley	120	09-12-19		N/A	
Festool plunge saw	1385	09-01-20		06-07-20	
Makita planer	751	09-12-19		10/05/20	
Spliter box	243	09-12-19		10/05/20	
Dewalt chop saw	785	17-01-20		17-06-20	
Dewalt chop saw	786	17-01-20		17-06-20	
Hoover	1214	07-02-20		10/05/20	
Hoover	1363	07-02-20		10/05/20	
Skill saw	705	07-02-20		10/05/20	
Chopsaw	814	07-02-20		10/05/20	
Infrared thermometer	13876	20-04-20		N/A	