

WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Sebastian st.

COMPILED & CHECKED BY : K.Kulsinskas

WEEK ENDING: 17/05/20

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
TOOL BOX	17	09/09/19		N/A	
TOOL BOX	15a	09/09/19		N/A	
TOOL BOX	11a	09/09/19		N/A	
110V LEAD	0008	09/09/19		01/11/20	
110V LEAD	0009	09/09/19		01/11/20	
110V LEAD	0010	09/09/19		01/11/20	
110V LEAD	83	09/09/19		01/11/20	
110V LEAD	78	09/09/19		01/11/20	
110 V SPLITTER BOX	1227	09/09/19		01/11/20	
Bosh jigsaw	1256	09/09/19		01/11/20	
Bosh hammer drill	1329	09/09/19		01/11/20	
Makita router 1/4	959	09/09/19		01/11/20	
Makita skilsaw	20984	09/09/19		01/11/20	
Makita planer	201	09/09/19		01/11/20	
Dewalt router 1/4	1026	09/09/19		01/11/20	
Hoover	1343	09/09/19		01/11/20	
A-Frame trolley	239	19/09/19		N/A	
Paslode gun 2fix	529	07-11-19		N/A	
Hoover	1303	07-11-19		01/11/20	
Splitter box	667	09-12-19		01/11/20	
Splitter box	28	09-12-19		01/11/20	
Task light	1304	09-12-19		01/11/20	
Task light	234	09-12-19		01/11/20	

A-Frame trolley	120	09-12-19	13-05-20	N/A	
Festool plunge saw	1385	09-01-20		01/11/20	
Makita planer	751	09-12-19		01/11/20	
Splitter box	243	09-12-19		01/11/20	
Dewalt chop saw	785	17-01-20		01/11/20	
Dewalt chop saw	786	17-01-20		01/11/20	
Hoover	1214	07-02-20		01/11/20	
Hoover	1363	07-02-20		01/11/20	
Skill saw	705	07-02-20		01/11/20	
Chopsaw	814	07-02-20		01/11/20	
Infrared thermometer	13876	20-04-20		N/A	
Hoover	1265	07-02-20		01/11/20	