

WEEKLY PLANT RETURN

AND PLANT SAFETY CHECK

SITE:

VSW - WOKI 02 & 03

COMPILED & CHECKED BY:

WEEK ENDING

05/09/21

J.Wray / A.Kulsinskas

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement

without delay Plant Item	I.D. No.	On Site	Off Site	Test Expiry	Condition of items/ other comments	
and lower Meason	4.64	<u>Date</u>	<u>Date</u>	<u>Date</u>		
WOKI 02			Line Called	ort order to	1. Islander in the end-on-	
Toolbox (on 1 st floor)	7A	20/02/2020	i Lastes Sir	N/A	Good Condition	
Toolbox (on 1 st floor)	14A	02/03/2020	II rangga	N/A	Good Condition	
Toolbox (on 1 st floor)	1A	02/03/2020	na osasika	N/A	Good Condition	
Toolbox (on 1 st floor)	16A	02/03/2020	1 00000	N/A	Good Condition	
Toolbox (on 1 st floor)	23A	12/06/2020	Little	N/A	Good Condition	
Toolbox (on 1 st floor)	17	15/07/2020	i nintahi	N/A	Good Condition	
Toolbox (small) in office	1026	22/06/2020	o masass	N/A	Good Condition	
Нор Up	1024	25/08/2020	01/09/21	N/A	Good Condition	
Hop Up	980	20/11/2020	01/09/21	N/A	Good Condition	
Hop Up	1035	20/11/2020		N/A	Good Condition	
2 nd Fix Paslode Gun	1382	07/10/2020		N/A	Good Condition	
2 nd Fix Paslode Gun	72	23/02/2020		N/A	Good Condition	
2 nd Fix Paslode Gun	991	01/04/2020		N/A	Good Condition	
A Frame	Big Blue	04/06/2020		N/A	Good Condition	
110v Lead	1266	20/02/2020		21/09/2021	Good Condition	
110v Lead	1253	20/02/2020	01/09/21	21/09/2021	Good Condition	
110v Lead	1394	20/10/2020		21/09/2021	Good Condition	
110v Lead	1395	20/10/2020	* " - v	21/09/2021	Good Condition	
110v Lead	1396	20/10/2020		21/09/2021	Good Condition	
110v Splitter Box	1241	20/02/2020		21/09/2021	Good Condition	
110v Splitter Box	649	12/06/2020	01/09/21	21/09/2021	Good Condition	
Dust Control Extractor	1363	12/06/2020		21/09/2021	Good Condition	
Dust Control Extractor	1353	13/10/2020		21/09/2021	Good Condition	
Dust Control Extractor	1264	15/07/2020	01/09/21	21/09/2021	Sent for Repair – Electrical Fault	
DeWalt Router ¼	660	20/02/2020	01/09/21	21/09/2021	Sent for Repair - Missing Depth Gauge	
Makita Router ½	67	20/02/2020	01/09/21	21/09/2021	Sent for Repair – Electrical Fault	
Makita Router ¼	1208	05/10/2020	1 1 1	21/09/2021	Good Condition	
DeWalt Chop saw	786	23/02/2021	01/09/21	21/09/2021	Good Condition	
DeWalt Chop saw	989	27/04/2021		21/09/2021	Good Condition	
Makita Jigsaw	1276	20/02/2020	4) - x 1;3	21/09/2021	Good Condition	
Makita Skill saw	622	20/02/2020		21/09/2021	Good Condition	
Festool saw	1385	07/10/2020		21/09/2021	Good Condition	
Festool Guide	R1	07/10/2020		N/A	Good Condition	
Festool Guide	R2	07/10/2020		N/A	Good Condition	

	The state of the state of	- In-		CREATION DATE:	07/02/2013	
DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	LAST REVISION DATE:	04/07/2013	Page 1 of 1
DOCUMENT OWNER:	DAS	12.10.0.1.1.0	3 5 2 3 5	NEXT REVIEW DATE:	07/02/2014	