

WEEKLY PLANT RETURN

AND PLANT SAFETY CHECK

<u>SITE:</u> VSW – WOKI 02 & 03

COMPILED & CHECKED BY:

J.Wray / A.Kulsinskas

WEEK ENDING

12/09/21

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement

without delay

<u>Plant Item</u>	I.D. No.	On Site	Off Site	Test Expiry	Condition of items/
·		<u>Date</u>	<u>Date</u>	<u>Date</u>	other comments
WOKI 02			-		
Toolbox (on 1 st floor)	7A	20/02/2020	10	N/A	Good Condition
Toolbox (on 1 st floor)	14A	02/03/2020	×	N/A	Good Condition
Toolbox (on 1 st floor)	1A	02/03/2020		N/A	Good Condition
Toolbox (on 1 st floor)	16A	02/03/2020		N/A	Good Condition
Toolbox (on 1 st floor)	23A	12/06/2020	6	N/A	Good Condition
Toolbox (on 1 st floor)	17	15/07/2020		N/A	Good Condition
Toolbox (small) in office	1026	22/06/2020		N/A	Good Condition
Hop Up	1035	20/11/2020	¥.	N/A	Good Condition
2 nd Fix Paslode Gun	1382	07/10/2020	1	N/A	Good Condition
2 nd Fix Paslode Gun	72	23/02/2020		N/A	Good Condition
2 nd Fix Paslode Gun	991	01/04/2020		N/A	Good Condition
A Frame	Big Blue	04/06/2020		N/A	Good Condition
110v Lead	1266	20/02/2020	*	21/09/2021	Good Condition
110v Lead	1253	20/02/2020		21/09/2021	Good Condition
110v Lead	1394	20/10/2020		21/09/2021	Good Condition
110v Lead	1395	20/10/2020		21/09/2021	Good Condition
110v Lead	1396	20/10/2020		21/09/2021	Good Condition
Dust Control Extractor	1363	12/06/2020		21/09/2021	Good Condition
Dust Control Extractor	1353	13/10/2020		21/09/2021	Good Condition
Makita Router ¼	1208	05/10/2020		21/09/2021	Good Condition
DeWalt Chop saw	989	27/04/2021		21/09/2021	Good Condition
Makita Jigsaw	1276	20/02/2020		21/09/2021	Good Condition
Makita Skill saw	622	20/02/2020		21/09/2021	Good Condition
Festool saw	1385	07/10/2020		21/09/2021	Good Condition
Festool Guide	R1	07/10/2020		N/A	Good Condition
Festool Guide	R2	07/10/2020	•	N/A	Good Condition
Makita Planer	161	05/10/2020		21/09/2021	Good Condition
Makita Multi Tool	1280	07/10/2020		21/09/2021	Good Condition
Makita Planer	751	23/02/2021	e -	21/09/2021	Good Condition
Scaffold Tower	RCL 08	23/03/2021	7 -	N/A	Good Condition
Makita Cold Cutter	1349	27/05/2021		21/09/2021	Good Condition
9 0					
,					6 - 10 - 10 - 10 - 10 - 10 - 10 - 10 - 1
č					

DOCUMENT REFERENCE: SIT-FM-011 DOCUMENT OWNER: DAS VERSION N	0: 1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	--------	--	--	-------------

0					
<u>Plant Item</u>	I.D. No.	<u>On Site</u>	Off Site	Test Expiry	Condition of items/
		<u>Date</u>	<u>Date</u>	<u>Date</u>	other comments
WOKI 03			61	4.	
Toolbox (in carpark)	25A	12/06/2020		N/A	Good Condition
Toolbox (in carpark)	8A	15/07/2020	Δ	N/A	Good Condition
Toolbox (in carpark)	No number	01/09/2021		N/A	Good Condition
110v Lead	13	20/02/2020		21/09/2021	Good Condition
110v Lead	1247	20/02/2020		21/09/2021	Good Condition
110v Lead	1263	20/02/2020	W	21/09/2021	Good Condition
110v Splitter Box	246	05/10/2020		21/09/2021	Good Condition
Dust Control Extractor	1343	20/10/2020	e	21/09/2021	Good Condition
Makita Hammer Drill	361	20/10/2020		21/09/2021	Good Condition
DeWalt Chop saw	785	27/04/2021		21/09/2021	Good Condition
i					