

WEEKLY PLANT RETURN

<u>AND</u> **PLANT SAFETY CHECK**

<u>SITE:</u> VSW – WOKI 02 & <mark>03</mark>

COMPILED & CHECKED BY:

WEEK ENDING

19/09/21

J.Wray / A.Kulsinskas

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement

without delay

| Plant Item | I.D. No. | On Site | Off Site | Test Expiry | Condition of items/ | |
|------------------------------------|----------|-------------|-------------|-------------|-----------------------|--|
| | | <u>Date</u> | <u>Date</u> | <u>Date</u> | other comments | |
| WOKI 02 | | | 1 14 6 | | A SERVE SHEW I | |
| Toolbox (on 1 st floor) | 7A | 20/02/2020 | | N/A | Good Condition | |
| Toolbox (on 1 st floor) | 14A | 02/03/2020 | N/A | | Good Condition | |
| Toolbox (on 1 st floor) | 1A | 02/03/2020 | - · | N/A | Good Condition | |
| Toolbox (on 1 st floor) | 16A | 02/03/2020 | | N/A | Good Condition | |
| Toolbox (on 1 st floor) | 23A | 12/06/2020 | | N/A | Good Condition | |
| Toolbox (on 1 st floor) | 17 | 15/07/2020 | | N/A | Good Condition | |
| Toolbox (small) in office | 1026 | 22/06/2020 | | N/A | Good Condition | |
| Нор Up | 1035 | 20/11/2020 | | N/A | Good Condition | |
| 2 nd Fix Paslode Gun | 1382 | 07/10/2020 | | N/A | Good Condition | |
| 2 nd Fix Paslode Gun | 72 | 23/02/2020 | | N/A | Good Condition | |
| 2 nd Fix Paslode Gun | 991 | 01/04/2020 | | N/A | Good Condition | |
| A Frame | Big Blue | 04/06/2020 | | N/A | Good Condition | |
| 110v Lead | 1266 | 20/02/2020 | | 21/09/2021 | Good Condition | |
| 110v Lead | 1253 | 20/02/2020 | | 21/09/2021 | Good Condition | |
| 110v Lead | 1394 | 20/10/2020 | | 21/09/2021 | Good Condition | |
| 110v Lead | 1395 | 20/10/2020 | | 21/09/2021 | Good Condition | |
| 110v Lead | 1396 | 20/10/2020 | | 21/09/2021 | Good Condition | |
| Dust Control Extractor | 1363 | 12/06/2020 | 100 | 21/09/2021 | Good Condition | |
| Dust Control Extractor | 1353 | 13/10/2020 | | 21/09/2021 | Good Condition | |
| Makita Router ¼ | 1208 | 05/10/2020 | | 21/09/2021 | Good Condition | |
| DeWalt Chop saw | 989 | 27/04/2021 | | 21/09/2021 | Good Condition | |
| Makita Jigsaw | 1276 | 20/02/2020 | 21/09/2021 | | Good Condition | |
| Makita Skill saw | 622 | 20/02/2020 | | 21/09/2021 | Good Condition | |
| Festool saw | 1385 | 07/10/2020 | 100 | 21/09/2021 | Good Condition | |
| Festool Guide | R1 | 07/10/2020 | | N/A | Good Condition | |
| Festool Guide | R2 | 07/10/2020 | | N/A | Good Condition | |
| Makita Planer | 161 | 05/10/2020 | | 21/09/2021 | Good Condition | |
| Makita Multi Tool | 1280 | 07/10/2020 | | 21/09/2021 | Good Condition | |
| Makita Planer | 751 | 23/02/2021 | | 21/09/2021 | Good Condition | |
| Scaffold Tower | RCL 08 | 23/03/2021 | | N/A | Good Condition | |
| Makita Cold Cutter | 1349 | 27/05/2021 | | 21/09/2021 | Good Condition | |
| | | | | | | |
| | | | | | | |
| | | | | A | | |

| DOCUMENT REFERENCE: DOCUMENT OWNER: | SIT-FM-011 DAS | VERSION NO: | 1.1 | CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE: | 07/02/2013 04/07/2013 07/02/2014 | Page 1 of 1 | |
|--|-------------------|-------------|-----|--|--|-------------|--|
|--|-------------------|-------------|-----|--|--|-------------|--|