



## WEEKLY PLANT RETURN

### AND

## PLANT SAFETY CHECK

**SITE: 25 Cannon Street**

**COMPILED & CHECKED BY:** A. Kulsinskas

**WEEK ENDING 26/09/21**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Printer Epson	1405	22/09/21		23/12/21	New
Toolbox	3A	19/07/21		N/A	Good
Toolbox	10A	19/07/21		N/A	Good
Toolbox	41A	19/07/21		N/A	Good
110v Extension Lead	2001	19/07/21		23/12/21	Good
110v Extension Lead	2002	19/07/21		23/12/21	Good
110v Extension Lead	2003	19/07/21		23/12/21	Good
110v Extension Lead	2004	19/07/21		23/12/21	Good
110V Splitter box	643	19/07/21		23/12/21	Good
Small Makita Skill Saw	1043	19/07/21		23/12/21	Good
Dust Extractor	1265	19/07/21		23/12/21	Good
Makita Planer	942	19/07/21		23/12/21	Good
2 <sup>nd</sup> fix Paslode Gun	1255	19/07/21		23/12/21	Good
DeWalt Chop Saw	676	19/07/21		23/12/21	Good
Bosch Jigsaw	184	19/07/21		23/12/21	Good
Bosch Hammer Drill	1329	19/07/21		23/12/21	Good
Dewalt ¼ Router	1403	19/07/21		23/12/21	Good
Podium Steps	SW03	19/07/21		N/A	Good
A Frame trolley	5	21/09/21		N/A	Good
Desk	No ID	22/07/21		N/A	Good
Desk	No ID	22/07/21		N/A	Good
Chair	No ID	22/07/21		N/A	Good
Chair	No ID	22/07/21		N/A	Good

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	Page 1 of 1
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	



## WEEKLY PLANT RETURN

### AND

## PLANT SAFETY CHECK

#### SITE:

VSW – WOKI 02 & 03

#### COMPILED & CHECKED BY:

J.Wray / K.Kulsinskas

#### WEEK ENDING

26/09/21

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
WOKI 02					
Toolbox (on 1 <sup>st</sup> floor)	7A	20/02/2020		N/A	Good Condition
Toolbox (on 1 <sup>st</sup> floor)	14A	02/03/2020		N/A	Good Condition
Toolbox (on 1 <sup>st</sup> floor)	1A	02/03/2020		N/A	Good Condition
Toolbox (on 1 <sup>st</sup> floor)	16A	02/03/2020		N/A	Good Condition
Toolbox (on 1 <sup>st</sup> floor)	23A	12/06/2020		N/A	Good Condition
Toolbox (on 1 <sup>st</sup> floor)	17	15/07/2020		N/A	Good Condition
Toolbox (small) in office	1026	22/06/2020		N/A	Good Condition
Hop Up	1035	20/11/2020		N/A	Good Condition
2 <sup>nd</sup> Fix Paslode Gun	1382	07/10/2020		N/A	Good Condition
2 <sup>nd</sup> Fix Paslode Gun	72	23/02/2020		N/A	Good Condition
2 <sup>nd</sup> Fix Paslode Gun	991	01/04/2020		N/A	Good Condition
A Frame	Big Blue	04/06/2020		N/A	Good Condition
110v Lead	1266	20/02/2020		21/09/2021	Good Condition
110v Lead	1253	20/02/2020		21/09/2021	Good Condition
110v Lead	1394	20/10/2020		21/09/2021	Good Condition
110v Lead	1395	20/10/2020		21/09/2021	Good Condition
110v Lead	1396	20/10/2020		21/09/2021	Good Condition
Dust Control Extractor	1363	12/06/2020		21/09/2021	Good Condition
Dust Control Extractor	1353	13/10/2020		21/09/2021	Good Condition
Makita Router ¼	1208	05/10/2020		21/09/2021	Good Condition
DeWalt Chop saw	989	27/04/2021		21/09/2021	Good Condition
Makita Jigsaw	1276	20/02/2020		21/09/2021	Good Condition
Makita Skill saw	622	20/02/2020		21/09/2021	Good Condition
Festool saw	1385	07/10/2020		21/09/2021	Good Condition
Festool Guide	R1	07/10/2020		N/A	Good Condition
Festool Guide	R2	07/10/2020		N/A	Good Condition
Makita Planer	161	05/10/2020		21/09/2021	Good Condition
Makita Multi Tool	1280	07/10/2020		21/09/2021	Good Condition
Makita Planer	751	23/02/2021		21/09/2021	Good Condition
Scaffold Tower	RCL 08	23/03/2021		N/A	Good Condition
Makita Cold Cutter	1349	27/05/2021		21/09/2021	Good Condition

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
WOKI 03					
Toolbox (in carpark)	25A	12/06/2020		N/A	Good Condition
Toolbox (in carpark)	8A	15/07/2020		N/A	Good Condition
Toolbox (in carpark)	No number	01/09/2021		N/A	Good Condition
110v Lead	13	20/02/2020		21/09/2021	Good Condition
110v Lead	1247	20/02/2020		21/09/2021	Good Condition
110v Lead	1263	20/02/2020		21/09/2021	Good Condition
110v Splitter Box	246	05/10/2020		21/09/2021	Good Condition
Dust Control Extractor	1343	20/10/2020		21/09/2021	Good Condition
Makita Hammer Drill	361	20/10/2020		21/09/2021	Good Condition
DeWalt Chop saw	785	27/04/2021		21/09/2021	Good Condition