



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE:

VSW – WOKI 02 & 03

COMPILED & CHECKED BY:

J.Wray / K.Kulsinkas

WEEK ENDING

10/10/21

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
WOKI 02					
Toolbox (on 1 st floor)	7A	20/02/2020		N/A	Good Condition
Toolbox (on 1 st floor)	14A	02/03/2020		N/A	Good Condition
Toolbox (on 1 st floor)	1A	02/03/2020		N/A	Good Condition
Toolbox (on 1 st floor)	16A	02/03/2020		N/A	Good Condition
Toolbox (on 1 st floor)	23A	12/06/2020		N/A	Good Condition
Toolbox (on 1 st floor)	17	15/07/2020		N/A	Good Condition
Toolbox (small) in office	1026	22/06/2020		N/A	Good Condition
Hop Up	1035	20/11/2020		N/A	Good Condition
2 nd Fix Paslode Gun	1382	07/10/2020		N/A	Good Condition
2 nd Fix Paslode Gun	72	23/02/2020		N/A	Good Condition
2 nd Fix Paslode Gun	991	01/04/2020		N/A	Good Condition
A Frame	Big Blue	04/06/2020		N/A	Good Condition
110v Lead	1266	20/02/2020		21/09/2021	Good Condition
110v Lead	1253	20/02/2020		21/09/2021	Good Condition
110v Lead	1394	20/10/2020		21/09/2021	Good Condition
110v Lead	1395	20/10/2020		21/09/2021	Good Condition
110v Lead	1396	20/10/2020		21/09/2021	Good Condition
Dust Control Extractor	1363	12/06/2020		21/09/2021	Good Condition
Dust Control Extractor	1353	13/10/2020		21/09/2021	Good Condition
Makita Router ¼	1208	05/10/2020		21/09/2021	Good Condition
DeWalt Chop saw	989	27/04/2021		21/09/2021	Good Condition
Makita Jigsaw	1276	20/02/2020		21/09/2021	Good Condition
Makita Skill saw	622	20/02/2020		21/09/2021	Good Condition
Festool saw	1385	07/10/2020		21/09/2021	Good Condition
Festool Guide	R1	07/10/2020		N/A	Good Condition
Festool Guide	R2	07/10/2020		N/A	Good Condition
Makita Planer	161	05/10/2020		21/09/2021	Good Condition
Makita Multi Tool	1280	07/10/2020		21/09/2021	Good Condition
Makita Planer	751	23/02/2021		21/09/2021	Good Condition
Scaffold Tower	RCL 08	23/03/2021		N/A	Good Condition
Makita Cold Cutter	1349	27/05/2021		21/09/2021	Good Condition

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	Page 1 of 1
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
WOKI 03					
Toolbox (in carpark)	25A	12/06/2020		N/A	Good Condition
Toolbox (in carpark)	8A	15/07/2020		N/A	Good Condition
Toolbox (in carpark)	No number	01/09/2021		N/A	Good Condition
110v Lead	13	20/02/2020		21/09/2021	Good Condition
110v Lead	1247	20/02/2020		21/09/2021	Good Condition
110v Lead	1263	20/02/2020		21/09/2021	Good Condition
110v Splitter Box	246	05/10/2020		21/09/2021	Good Condition
Dust Control Extractor	1343	20/10/2020		21/09/2021	Good Condition
Makita Hammer Drill	361	20/10/2020		21/09/2021	Good Condition
DeWalt Chop saw	785	27/04/2021		21/09/2021	Good Condition