



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 25 Cannon Street

COMPILED & CHECKED BY: A. Kulsinkas

WEEK ENDING 21/11/21

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u> | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u> |
|---------------------------------|-----------------|---------------------|----------------------|-------------------------|-----------------------------------------------|
| Printer Epson | 1405 | 22/09/21 | | 23/12/21 | Good |
| Toolbox | 3A | 19/07/21 | | N/A | Good |
| Toolbox | 10A | 19/07/21 | | N/A | Good |
| Toolbox | 41A | 19/07/21 | | N/A | Good |
| Toolbox | 1341 | 06/10/21 | | N/A | Good |
| Toolbox | 50 | 06.10.21 | | N/A | Good |
| Toolbox (small) | 4887 | 05/11/21 | | N/A | Good |
| 110v Extension Lead | 2001 | 19/07/21 | | 23/12/21 | Good |
| 110v Extension Lead | 2002 | 19/07/21 | | 23/12/21 | Good |
| 110v Extension Lead | 2003 | 19/07/21 | | 23/12/21 | Good |
| 110v Extension Lead | 2004 | 19/07/21 | | 23/12/21 | Good |
| 110V Splitter box | 643 | 19/07/21 | | 23/12/21 | Good |
| 110V Splitter box | 758 | 05/11/21 | | 6/02/22 | Good |
| Makita Multi tool | 1380 | 06/10/21 | | 07/01/22 | Good |
| Small Makita Skill Saw | 1043 | 19/07/21 | | 23/12/21 | Good |
| Festool plunge saw | 1401 | 26/10/21 | | 27/01/22 | Good |
| Dust Extractor | 1265 | 19/07/21 | | 23/12/21 | Good |
| Dust Extractor | 1242 | 26/10/21 | | 05/01/22 | Good |
| Makita Planer | 942 | 19/07/21 | | 23/12/21 | Good |
| 2 nd fix Paslode Gun | 1255 | 19/07/21 | | 23/12/21 | Good |
| DeWalt Chop Saw | 676 | 19/07/21 | | 23/12/21 | Good |
| Bosch Jigsaw | 184 | 19/07/21 | | 23/12/21 | Good |
| Bosch Hammer Drill | 1329 | 19/07/21 | | 23/12/21 | Good |
| Dewalt ¼ Router | 1403 | 19/07/21 | | 23/12/21 | Good |
| Podium Steps | SW03 | 19/07/21 | | N/A | Good |
| A Frame trolley | 5 | 21/09/21 | | N/A | Good |
| Desk | No ID | 22/07/21 | | N/A | Good |
| Desk | No ID | 22/07/21 | | N/A | Good |
| Chair | No ID | 22/07/21 | | N/A | Good |
| Chair | No ID | 22/07/21 | | N/A | Good |



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE:

VSW – WOKI - 03

COMPILED & CHECKED BY:

J.Wray / K.Kulsinskas

WEEK ENDING

21/11/21

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u> | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/ other comments</u> |
|---------------------------------|-----------------|---------------------|----------------------|-------------------------|-----------------------------------------------|
| Toolbox (carpark level 03) | 7A | 20/02/2020 | | N/A | Good Condition |
| Toolbox (carpark level 03) | 14A | 02/03/2020 | | N/A | Good Condition |
| Toolbox (carpark level 03) | 1A | 02/03/2020 | | N/A | Good Condition |
| Toolbox (carpark level 03) | 16A | 02/03/2020 | | N/A | Good Condition |
| Toolbox (carpark level 03) | 23A | 12/06/2020 | | N/A | Good Condition |
| Toolbox (carpark level 03) | 17 | 15/07/2020 | | N/A | Good Condition |
| Toolbox (small) in office | 1026 | 22/06/2020 | | N/A | Good Condition |
| Toolbox (carpark level 02) | 25A | 12/06/2020 | | N/A | Good Condition |
| Toolbox (carpark level 03) | 8A | 15/07/2020 | | N/A | Good Condition |
| Toolbox (carpark level 03) | No number | 01/09/2021 | | N/A | Good Condition |
| Hop Up | 1035 | 20/11/2020 | | N/A | Good Condition |
| 2 nd Fix Paslode Gun | 1382 | 07/10/2020 | | N/A | Good Condition |
| 2 nd Fix Paslode Gun | 991 | 01/04/2020 | | N/A | Good Condition |
| A Frame | Big Blue | 04/06/2020 | | N/A | Good Condition |
| 110v Lead | 1266 | 20/02/2020 | | 15/01/2022 | Good Condition |
| 110v Lead | 1253 | 20/02/2020 | | 15/01/2022 | Good Condition |
| 110v Lead | 1394 | 20/10/2020 | | 15/01/2022 | Good Condition |
| 110v Lead | 1395 | 20/10/2020 | | 15/01/2022 | Good Condition |
| 110v Lead | 1396 | 20/10/2020 | | 15/01/2022 | Good Condition |
| 110v Lead | 13 | 20/02/2020 | | 15/01/2022 | Good Condition |
| 110v Lead | 1247 | 20/02/2020 | | 15/01/2022 | Good Condition |
| 110v Lead | 1263 | 20/02/2020 | | 15/01/2022 | Good Condition |
| 110v Splitter Box | 246 | 05/10/2020 | | 15/01/2022 | Good Condition |
| Dust Control Extractor | 1363 | 12/06/2020 | | 15/01/2022 | Good Condition |
| Dust Control Extractor | 1353 | 13/10/2020 | | 15/01/2022 | Good Condition |
| Dust Control Extractor | 1343 | 20/10/2020 | | 15/01/2022 | Good Condition |
| Makita Router ¼ | 1208 | 05/10/2020 | | 15/01/2022 | Good Condition |
| DeWalt Chop saw | 989 | 27/04/2021 | | 15/01/2022 | Good Condition |
| DeWalt Chop saw | 785 | 27/04/2021 | | 15/01/2022 | Good Condition |
| Makita Jigsaw | 1276 | 20/02/2020 | | 15/01/2022 | Good Condition |
| Makita Skill saw | 622 | 20/02/2020 | | 15/01/2022 | Good Condition |
| Festool saw | 1385 | 07/10/2020 | | 15/01/2022 | Good Condition |
| Festool Guide | R1 | 07/10/2020 | | N/A | Good Condition |
| Festool Guide | R2 | 07/10/2020 | | N/A | Good Condition |
| Makita Planer | 751 | 23/02/2021 | | 15/01/2022 | Good Condition |
| Makita Planer | 161 | 05/10/2020 | | 15/01/2022 | Good Condition |
| Makita Multi Tool | 1280 | 07/10/2020 | | 15/01/2022 | Good Condition |
| Makita Cold Cutter | 1349 | 27/05/2021 | | 15/01/2022 | Good Condition |
| Makita Hammer Drill | 361 | 20/10/2020 | | 15/01/2022 | Good Condition |