



## WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

**SITE: 21m**

**COMPILED & CHECKED BY: J. WRAY**

**WEEK ENDING: 05.06.21**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	04.10.21		N/A	
Long Pallet truck	1422	04.10.21		N/A	
Short Pallet truck	1384	16.05.22	31/05/22	N/A	Pallet Truck kept at JMS as apparently it was theirs ?
Short Pallet truck	02 ?	01/06/22		N/A	New - H/O to confirm plant number
Delta Deck	1402	04.10.21		N/A	
Delta Deck	1414	16.05.22		N/A	
Delta Deck	1415	16.05.22		N/A	
Toolbox	1340	04.10.21		N/A	located on level 6
Toolbox	11A	04.10.21		N/A	located on level 3
Toolbox	32A	04.10.21		N/A	located on level 3
Toolbox	1423	04.10.21		N/A	located on level 4
Toolbox	A2	24.03.22		N/A	located on level 3
Toolbox	L17	06/04/22		N/A	located on level 3
Toolbox	8A	16.05.22		N/A	located on level 4
Toolbox	1424	16.05.22		N/A	located on level 3
Toolbox	1341	16.05.22		N/A	located on level 4
110V Leads Numbers : 83 , 471 , 0009 , 0008 , 1225 , 1392	See across	04.10.21		30.07.22	
110V Leads Numbers : 0006 , 1284 , 0001 , 1344	See across	17.03.22		30.07.22	
Bosch Hammer drill	934	04.10.21		30.07.22	
Bosch pistol drill	888	04.10.21		30.07.22	
Makita Router	959	24.03.22		18.07.22	
Dust Extractor	1344	24.03.22		30.07.22	
Paslode Straight pin gun	72	17.03.22		N/A	Need Cleaning
Paslode Straight pin gun	169	17.03.22		N/A	Need Cleaning
Plastic bench stools	???	17.03.22		N/A	MISSING AT PRESENT (1 NO FOUND)
Makita Skill Saw	1413	24.03.22		30.10.22	
Makita Jigsaw	137	???????	17/05/22	30.10.22	TAKEN BY JOE TO MLGH
12v Caulking Gun & Charger	1416	16.05.22		16.08.22	
Dewalt Battery Task Light	1417	16.05.22			Inc battery
Dewalt Battery Task Light	1418	16.05.22			Inc battery
Dewalt Battery Task Light	1419	16.05.22			Inc battery



## WEEKLY PLANT RETURN

### AND

## PLANT SAFETY CHECK

**SITE: Hoxton Hotel**

**COMPILED & CHECKED BY:**

A.Kulsinskas

**WEEK ENDING 05/06/22**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Printer Epson	1405	10/05/22		08/07/22	Good
Toolbox	7A	25/04/22		N/A	Good
Toolbox	1A	25/04/22		N/A	Good
Toolbox	16	26/04/22		N/A	Good
Toolbox		17/05/22		N/A	Good
Makita Hammer drill	330	26/04/22		04/07/22	Good
Metabolo pistol drill	758	26/04/22		04/07/22	Good
Milwaukee Mastic gun	1412	02/05/22		N/A	Good
110v Lead	0014	25/04/22		04/07/22	Good
110v Lead	0015	25/04/22		04/07/22	Good
110v Lead	0016	25/04/22		04/07/22	Good
110v Lead	0017	25/04/22		04/07/22	Good
110v splitter box	238A	25/04/22		04/07/22	Good
Splitbox	684	17/05/22			Good
Task Light	34	25/04/22		04/07/22	Good
Task Light	1309	25/04/22		04/07/22	Good
Dewalt Router	1361	25/05/22		04/07/22	Good
Dewalt Router	1357	25/05/22		04/07/22	Good
Green A Frame trolley		26/04/22		N/A	Good
Dewalt chapsaw	795	25/04/22			Blade guard rollers missing and dusk extraction kit faulty. Not in use.
Dewalt Chop saw	989	11/05/22		11.08.22	Good
Paslode 2 <sup>nd</sup> fix gun angled	1014	25/04/22		N/A	Good
Paslode 2 <sup>nd</sup> fix gun straight	529	25/04/22		N/A	Good
Makita skillsaw	622	25/05/22		04/07/22	Good
Dust extractor	1304	25/04/22		04/07/22	Good
Dust extractor	1420	25/04/22		04/07/22	Good
Dust extractor	1242	17/05/22		08/07/22	Good
Hop Up	1035	05/04/22		N/A	Good
Hop Up		17/05/22		N/A	Good
Festool Plunge Saw	1401	17/05/22		08/07/22	Good
Battery Dewalt chapsaw	1409	23/05/22		N/A	Good

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	Page 1 of 1
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	