

WEEKLY PLANT RETURN

AND PLANT SAFETY CHECK

SITE: Hoxton Hotel

COMPILED & CHECKED BY:

A.Kulsinskas

WEEK ENDING 07/08/22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
Printer Epson	1405	10/05/22	,-	04/10/22	Good
Toolbox	7A	25/04/22	2	N/A	Good
Toolbox (Rama)	1A	25/04/22	-	N/A	Good
Toolbox (Tibor)	16	26/04/22		N/A	Good
Toolbox (small ½)		06/06/22		N/A	Good
Toolbox (Gena)	A:10	15/06/22		N/A	Good
Toolbox (Alex)	. 9A	15/06/22		N/A	Good
Toolbox (Fixings)	1026	20/06/22	r -	N/A	Good
Makita Hammer drill	330	26/04/22		04/10/22	Good
Metabolo pistol drill	758	26/04/22		04/10/22	Good
Milwaukee Mastic gun.	1412	02/05/22	-	N/A	Good
110v Lead	0014	25/04/22		04/10/22	Good
110v Lead	0015	25/04/22		04/10/22	Good
110v Lead	0016	25/04/22		20/09/22	Good
110v Lead	0017	25/04/22		04/10/22	Good
110v Lead	0004	20/06/22		20/09/22	Good
110v Lead	1010a	04/07/22		04/10/22	Good
110v Lead	1267	04/07/22	e i	04/10/22	Good
110v splitter box	238A	25/04/22		04/10/22	Good
110v splitter box	930	20/06/22		20/09/22	Good
110v splitter box	684	17/05/22		04/10/22	Good
110v splitter box	643	20/06/22		04/10/22	Good
110v splitter box	758	04/07/22		04/10/22	Good
110v splitter box	1368	04/07/22		04/10/22	Good
Task Light	34	25/04/22		04/10/22	Good
Task Light	1309	25/04/22		04/10/22	Good
Task Light	34	20/06/22		20/09/22	Good
Task Light	1306	21/07/22	,	21/10/22	Good
Task Light	29	21/07/22		21/10/22	Good
Task Light	31	21/07/22		21/10/22	Good
Dewalt Router	1361	25/05/22	1 1	04/10/22	Good
Dewalt Router	1357	25/05/22	· · ·	04/07/22	Good

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------

Green A Frame trolly		26/04/22		N/A	Good
Dewalt chopsaw	795	25/04/22		04/10/22	Good
Dewalt Chop saw	989	11/05/22		04/10/22	Good
Makita Chopsaw	13453	15/06/22		15/09/22	Not in use send to repair
Marita planer	758	04/07/22		04/10/22	Good
Paslode 2 nd fix gun angled	1014	25/04/22		N/A	Good
Paslode 2 nd fix gun straight	529	25/04/22		N/A	Good
Paslode 2 nd fix gun straight	1255	20/06/22	0	N/A	Good
Dust extractor	1304	25/04/22		04/10/22	Good
Dust extractor	1420	25/04/22		04/10/22	Good
Dust extractor	1242	17/05/22		04/10/22	Good
Dust extractor	1264	15/06/22		10/09/22	Good
Dust extractor	1241	15/06/22		15/09/22	Good
Нор Up	1035	05/04/22		N/A	Good
Нор Up		17/05/22		N/A	Good
Нор Up	-	15/06/22	x	N/A	Good
Festool Plunge Saw	1401	17/05/22		04/10/22	Good
Battery Dewalt chopsaw	1409	23/05/22	**************************************	N/A	Good
Battery Dewalt planer	1410	23/05/22		N/A	Good
Battery Dewalt skillsaw	1406	23/05/22		N/A	Good
Battery Dewalt jigsaw	1408	23/05/22	-	N/A	Good
Battery Dewalt router	1407	23/05/22		N/A	Good
	14				P 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2

DOCUMENT REFERENCE: SIT-FM-01: DOCUMENT OWNER: DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 2 of 1
--	-------------	-----	--	--	---------------------------



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 21m

COMPILED & CHECKED BY: J. Wray

WEEK ENDING: 07.08.22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	04.10.21	-	N/A	
Long Pallet truck	1422	04.10.21	-	N/A	
Short Pallet truck	02 ?	01/06/22		N/A	New - H/O to confirm plant number
Delta Deck	1402	04.10.21	8	N/A	
Delta Deck (small)	1414	16.05.22	= .	N/A	
Delta Deck (small)	1415	16.05.22		N/A	
Delta Deck	????	14.07.22		N/A	**
Delta Deck	????	14.07.22		N/A	
Toolbox	1340	04.10.21		N/A	located on level 9
Toolbox	11A	04.10.21		N/A	located on level 3
Toolbox	32A	04.10.21		N/A	located on level 3
Toolbox	1423	04.10.21	e X	N/A	located on level 4
Toolbox	A2	24.03.22		N/A	located on level 3
Toolbox	L17	06/04/22		N/A	located on level 3
Toolbox	8A	16.05.22		N/A	located on level 4
Toolbox	1424	16.05.22	- p.	N/A	located on level 3
Toolbox	1341	16.05.22		N/A	located on level 4
Toolbox	1342	03.08.22		N/A	located on level 7
110V Leads Numbers : 83 , 471 , 0009 , 0008 , 1225 , 1392 110V Leads Numbers :	See across See	04.10.21		30.07.22	Needs retesting Needs retesting
0006 , 1284 , 0001 , 1344	across	17.03.22		30.07.22	No ada nata stina
Bosch Hammer drill	934	04.10.21		30.07.22	Needs retesting
Bosch pistol drill	888	04.10.21	*	30.07.22	Needs retesting
Makita Router	959	24.03.22		18.07.22	Needs retesting
Makita Router	1337	03.08.22		23/09/21	Needs retesting
Dewalt Router	1367	03.08.22	*	10/04/22	Needs retesting
Festool Router	VB001	03.08.22	1 7	13/11/21	Needs retesting – Owned by Vegas
Dust Extractor	1344	24.03.22	· · · · · · · · · · · · · · · · · · ·	30.07.22	Needs retesting
Paslode Straight pin gun	72	17.03.22	A A	N/A	Need Cleaning
Paslode Straight pin gun	169	17.03.22	V	N/A	Need Cleaning
Plastic bench stools	???	17.03.22		N/A	MISSING AT PRESENT (1 NO FOUND)
Makita Skill Saw	1413	24.03.22		30.10.22	

DOCUMENT REFERENCE: SIT-FM-011 DAS VERSION NO: 1.1 CREATION DATE: 07/02/2013 O1/03/2018 Page 1 of 1



Makita Jigsaw	137	???????	17/05/22	30.10.22	TAKEN BY JOE TO MLGH
12v Caulking Gun & Charger	1416	16.05.22		16.08.22	
Dewalt Battery Task Light	1417	16.05.22		N/A	Inc battery
Dewalt Battery Task Light	1418	16.05.22	* * * * * * * * * * * * * * * * * * * *	N/A	Inc battery
Dewalt Battery Task Light	1419	16.05.22	0	N/A	Inc battery
Dewalt Battery Task Light Charger	1421	23.05.22		23.08.22	
Chop Saw	33A	03.08.22		02.06.21	Needs retesting
		N			2
¥					
		-			
					3