

WEEKLY PLANT RETURN

AND PLANT SAFETY CHECK

SITE: Hoxton Hotel

COMPILED & CHECKED BY:

A.Kulsinskas

WEEK ENDING 18/09/22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
Printer Epson	1405	10/05/22		04/10/22	Good
Toolbox	-7A	25/04/22		N/A	Good
Toolbox (Rama)	1A	25/04/22		N/A	Good
Toolbox (Tibor)	16	26/04/22		N/A	Good
Toolbox (small ½)		06/06/22		N/A	Good
Toolbox (Gena)	A10	15/06/22		N/A	Good
Toolbox (Alex)	9A	15/06/22		N/A	Good
Toolbox (Fixings)	1026	20/06/22		N/A	Good
Makita Hammer drill	330	26/04/22		04/10/22	Good
Makita Hammer drill	361	14/09/22		14/12/22	Good
Bosch Hammer drill	941	14/09/22		14/12/22	Good
Metabolo pistol drill	758	26/04/22	6	04/10/22	Good
Milwaukee Mastic gun	1412	02/05/22		N/A	Good
110v Lead	0014	25/04/22		04/10/22	Good
110v Lead	0015	25/04/22		04/10/22	Good
110v Lead	0016	25/04/22		12/12/22	Good
110v Lead	0017	25/04/22		04/10/22	Good
110v Lead	0004	20/06/22	1	12/12/22	Good
110v Lead	1010a	04/07/22		04/10/22	Good
110v Lead	1267	04/07/22		04/10/22	Good
110v splitter box	238A	25/04/22	95	04/10/22	Good
110v splitter box	930	20/06/22		12/12/22	Good
110v splitter box	684	17/05/22		04/10/22	Good
110v splitter box	643	20/06/22	e e	04/10/22	Good
110v splitter box	758	04/07/22		04/10/22	Good
110v splitter box	1368	04/07/22	v	04/10/22	Good
Task Light	34	25/04/22		04/10/22	Good
Task Light	1309	25/04/22	18	04/10/22	Good
Task Light	34	20/06/22		12/12/22	Good
Task Light	1306	21/07/22		21/10/22	Good
Task Light	29	21/07/22		21/10/22	Good
Task Light	31	21/07/22	, i	21/10/22	Good

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------------	-------------	-----	--	--	-------------

Dewalt Router	1361	25/05/22		04/10/22	Good
Dewalt Router	1357	25/05/22	-	04/07/22	Good
Green A Frame trolly		26/04/22	ž.	N/A	Good
Dewalt chopsaw	795	25/04/22	24/08/22		Sent to repair – Harrow Tools
Dewalt Chop saw	989	11/05/22	1	04/10/22	Good
Makita Chopsaw	785	09/08/22		09/11/22	Good
Marita planer	758	04/07/22		04/10/22	Good
Paslode 2 nd fix gun angled	1014	25/04/22		N/A	Good
Paslode 2 nd fix gun straight	529	25/04/22		N/A	Good
Paslode 2 nd fix gun straight	1255	20/06/22		N/A	Good
Chain mortiser	673	24/08/22	10	24/11/22	Good
Dust extractor	1304	25/04/22		04/10/22	Good
Dust extractor	1420	25/04/22		04/10/22	Good
Dust extractor	1242	17/05/22	6	04/10/22	Good
Dust extractor	1264	15/06/22		12/12/22	Good
Dust extractor	1241	15/06/22	A N .	12/12/22	Good
Нор Up	1035	05/04/22	-	N/A	Good
Hop Up	*	17/05/22		N/A	Good
Нор Up		15/06/22		N/A	Good
Festool Plunge Saw	1401	17/05/22		04/10/22	Good
Battery Dewalt chopsaw	1409	23/05/22		N/A	Good
Battery Dewalt planer	1410	23/05/22	(40)	N/A	Good
Battery Dewalt skillsaw	1406	23/05/22		N/A	Good
Battery Dewalt jigsaw	1408	23/05/22		N/A	Good
Battery Dewalt router	1407	23/05/22	7	N/A	Good

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 2 of 1
--	-------------------	-------------	-----	--	--	-------------



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE:

REPTON GARDENS

COMPILED & CHECKED BY:

Slav Simonovic

WEEK ENDING: 18/09/2022

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
TOOLBOX	7A	05/09/22		N/A	· .
TOOLBOX	14A	05/09/22		N/A	
BOSCH PLANER	905	05/09/22	-	02/12/22	Good working order
DUST EXTRACTOR	1359	05/09/22		02/12/22	Good working order
MAKITA JIGSAW	1370	05/09/22		02/12/22	Good working order
BOSCH HAMMER DRILL	1329	05/09/22		02/12/22	Good working order
DEWALT CHOPSAW	690	05/09/22		02/12/22	Good working order
MAKITA SKILLSAW	706	05/09/22	-	02/12/22	Good working order
110V EXTENSION LEAD	211	05/09/22	, a	02/12/22	Good working order
110V EXTENSION LEAD	0020	05/09/22		02/12/22	Good working order
110V EXTENSION LEAD	0021	05/09/22		02/12/22	Good working order
110V EXTENSION LEAD	0022	05/09/22	*1	02/12/22	Good working order
FESTOOL SKILL SAW	1392	06/09/22		02/12/22	Good working order
110V SPLITTER BOX	63150	08/09/22		02/12/22	Good working order
HOP UP	0023	08/09/22		N/A	Good working order
*	-	20,00,00		1475	,
				100000000000000000000000000000000000000	

DOCUMENT REFERENCE: SIT-FM-011 VER DOCUMENT OWNER: DAS	RSION NO: 1.1	CREATION DATE: LAST REVISION DATE:	07/02/2013 01/03/2018	Page 1 of 1
--	---------------	---------------------------------------	--------------------------	-------------



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 21m

COMPILED & CHECKED BY: J. Wray / D. Sanders

WEEK ENDING: 18.09.22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry	Condition of items/ other comments
A France Trailless	202	04 10 31		Date N/A	
A Frame Trolley	393	04.10.21		N/A	
Long Pallet truck	1422	04.10.21	- 0	N/A	No. 11/O to confirm plant much a
Short Pallet truck	02 ?	01/06/22		N/A	New - H/O to confirm plant number
Delta Deck	1402	04.10.21		N/A	
Delta Deck (small)	1414	16.05.22		N/A	
Delta Deck (small)	1415	16.05.22		N/A	*
Delta Deck	????	14.07.22		N/A	
Delta Deck	????	14.07.22			
Toolbox	1340	04.10.21	7 0	N/A	located on level 9
Toolbox	11A	04.10.21		N/A	located on level 3
Toolbox	32A	04.10.21	(2)	N/A	located on level 3
Toolbox	1423	04.10.21		N/A	located on level 4
Toolbox	A2	24.03.22		N/A	located on level 3
Toolbox	L17	06/04/22	a Ç-	N/A	located on level 3
Toolbox	8A	16.05.22	- " .	N/A	located on level 4
Toolbox	1424	16.05.22		N/A	located on level 3
Toolbox	1341	16.05.22		N/A	located on level 4
Toolbox	1342	03.08.22	1	N/A	located on level 7
110V Leads Numbers : 83,0009,0008,1225,1392	See across	04.10.21		12.11.22	471 DEFECTIVE – THROWN AWAY
110V Leads Numbers : 0006 , 1284 , 0001 , 1344	See across	17.03.22		12.11.22	
Bosch Hammer drill	934	04.10.21		12.11.22	The second of th
Bosch pistol drill	888	04.10.21		12.11.22	
Makita Router	959	24.03.22	alteri işmen nançırınışı	12.11.22	
Makita Router	1337	03.08.22		12.11.22	
Dewalt Router	1367	03.08.22		12.11.22	1 2
Festool Router	VB001 (1967)	03.08.22		12.11.22	Owned by Vegas
Dust Extractor	1344	24.03.22		12.11.22	
Paslode Straight pin gun	72	17.03.22		N/A	
Paslode Straight pin gun	169	17.03.22		N/A	
Plastic bench stools	???	17.03.22		N/A	MISSING AT PRESENT (1 NO FOUND)
Makita Skill Saw	1413	24.03.22		12.11.22	

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE:	07/02/2013 01/03/2018	Page 1 of 1	
--	-------------------	-------------	-----	---------------------------------------	--------------------------	-------------	--