



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: REPTON GARDENS

COMPILED & CHECKED BY: Slav Simonovic

WEEK ENDING: 02/10/2022

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
TOOLBOX	7A	05/09/22		N/A	
TOOLBOX	14A	05/09/22		N/A	
BOSCH PLANER	905	05/09/22		02/12/22	Good working order
DUST EXTRACTOR	1359	05/09/22		02/12/22	Good working order
MAKITA JIGSAW	1370	05/09/22		02/12/22	Good working order
BOSCH HAMMER DRILL	1329	05/09/22		02/12/22	Good working order
DEWALT CHOPSAW	690	05/09/22		02/12/22	Good working order
MAKITA SKILLSAW	706	05/09/22		02/12/22	Good working order
110V EXTENSION LEAD	211	05/09/22		02/12/22	Good working order
110V EXTENSION LEAD	0020	05/09/22		02/12/22	Good working order
110V EXTENSION LEAD	0021	05/09/22		02/12/22	Good working order
110V EXTENSION LEAD	0022	05/09/22		02/12/22	Good working order
FESTOOL SKILL SAW	1392	06/09/22		02/12/22	Good working order
110V SPLITTER BOX	63150	08/09/22		02/12/22	Good working order
HOP UP	0023	08/09/22		N/A	Good working order
BISCUIT CUTTER	229	22/09/22		22/12/22	Good working order
PODIUM STEP	PS30	30/09/22		N/A	Good working order
PODIUM STEP	PS04	30/09/22		N/A	Good working order
TASK LIGHT	28A	22/09/22		22/12/22	Good working order



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 21m

COMPILED & CHECKED BY: J. Wray / D. Sanders

WEEK ENDING: 02.10.22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	04.10.21		N/A	
Long Pallet truck	1422	04.10.21		N/A	
Short Pallet truck	1442	01/06/22		N/A	New ID no to be marked on site
Delta Deck	1402	04.10.21		N/A	
Delta Deck (small)	1414	16.05.22		N/A	
Delta Deck (small)	1415	16.05.22		N/A	
Delta Deck	1425	14.07.22		N/A	New ID no to be marked on site
Delta Deck	1426	14.07.22		N/A	New ID no to be marked on site
Hop Up	1438	20.09.22		N/A	New ID no to be marked on site
Hop Up	1439	20.09.22		N/A	New ID no to be marked on site
Hop Up	1440	20.09.22		N/A	New ID no to be marked on site
Hop Up	1441	20.09.22		N/A	New ID no to be marked on site
Hop Up	979	28.09.22		N/A	
Hop Up	1018	28.09.22		N/A	
Toolbox	1340	04.10.21		N/A	located on level 9
Toolbox	11A	04.10.21		N/A	located on level 3
Toolbox	32A	04.10.21		N/A	located on level 3
Toolbox	1423	04.10.21		N/A	located on level 4
Toolbox	A2	24.03.22		N/A	located on level 3
Toolbox	L17	06/04/22		N/A	located on level 3
Toolbox	8A	16.05.22		N/A	located on level 4
Toolbox	1424	16.05.22		N/A	located on level 3
Toolbox	1341	16.05.22		N/A	located on level 4
Toolbox	1342	03.08.22		N/A	located on level 7
Toolbox	4A	20.09.22		N/A	
110V Leads Numbers : 83 , 0009 , 0008 , 1225 , 1392	See across	04.10.21		12.11.22	471 DEFECTIVE – THROWN AWAY
110V Leads Numbers : 0006 , 1284 , 0001 , 1344	See across	17.03.22		12.11.22	
Bosch Hammer drill	934	04.10.21		12.11.22	
Bosch pistol drill	888	04.10.21		12.11.22	
Makita Router	959	24.03.22		12.11.22	
Makita Router	1337	03.08.22		12.11.22	

[illegible]