

#### **WEEKLY PLANT RETURN**

## AND PLANT SAFETY CHECK

**SITE:** Hoxton Hotel

### **COMPILED & CHECKED BY:**

A.Kulsinskas

#### **WEEK ENDING 16/10/22**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
Printer Epson	1405	10/05/22		29/12/22	Good
Toolbox	7A	25/04/22		N/A	Good
Toolbox (Rama)	1A	25/04/22		N/A	Good
Toolbox (Tibor)	16	26/04/22	- ×	N/A	Good
Toolbox (small ½ )		06/06/22		N/A	Good
Toolbox (Gena)	A10	15/06/22	ĺ.	N/A	Good
Toolbox (Alex)	9A	15/06/22		N/A	Good
Toolbox (Fixings)	1026	20/06/22		N/A	Good
Makita Hammer drill	330	26/04/22	۰	29/12/22	Good
Makita Hammer drill	361	14/09/22		14/12/22	Good
Bosch Hammer drill	941	14/09/22		14/12/22	Good
Metabolo pistol drill	758	26/04/22	7	04/10/22	Good
Milwaukee Mastic gun	. 1412	02/05/22		N/A	Good
110v Lead	0014	25/04/22	* 4	29/12/22	Good
110v Lead	0015	25/04/22	9	29/12/22	Good
110v Lead	0016	25/04/22		12/12/22	Good
110v Lead	0017	25/04/22		29/12/22	Good
110v Lead	0004	20/06/22	* 6	12/12/22	Good
110v Lead	1010a	04/07/22		29/12/22	Good
110v Lead	1267	04/07/22		29/12/22	Good
110v splitter box	238A	25/04/22		29/12/22	Good
110v splitter box	930	20/06/22		12/12/22	Good
110v splitter box	684	17/05/22		29/12/22	Good
110v splitter box	643	20/06/22	8	29/12/22	Good
110v splitter box	758	04/07/22		29/12/22	Good
110v splitter box	1368	04/07/22		29/12/22	Good
Task Light	34	25/04/22		29/12/22	Good
Task Light	1309	25/04/22		29/12/22	Good
Task Light	34	20/06/22		12/12/22	Good
Task Light	1306	21/07/22	Turk tracks	21/10/22	Good
Task Light	. 29	21/07/22	and the same	21/10/22	Good
Task Light	31	21/07/22		21/10/22	Good

DOCUMENT REFERENCE: SIT-FM-011 DOCUMENT OWNER: DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 1
--	-------------	-----	--	--	-------------

-3					
Dewalt Router	1361	25/05/22		29/12/22	Good
Dewalt Router	1357	25/05/22		29/12/22	Good
Green A Frame trolly		26/04/22		N/A	Good
Dewalt chopsaw	795	25/04/22	24/08/22	The second of	Sent to repair – Harrow Tools
Dewalt Chop saw	989	11/05/22		29/12/22	Good
Makita Chopsaw	785	09/08/22		09/11/22	Good
Makita planer	758	04/07/22		29/12/22	Good
Paslode 2 <sup>nd</sup> fix gun angled	1014	25/04/22	2.5	N/A	Good
Paslode 2 <sup>nd</sup> fix gun straight	529	25/04/22		N/A	Good
Paslode 2 <sup>nd</sup> fix gun straight	1255	20/06/22		N/A	Good
Chain mortiser	673	24/08/22	3	24/11/22	Good
Dust extractor	1304	25/04/22		29/12/22	Good
Dust extractor	1420	25/04/22		29/12/22	Good
Dust extractor	1242	17/05/22		29/12/22	Good
Dust extractor	1264	15/06/22		12/12/22	Good
Dust extractor	1241	15/06/22		12/12/22	Good
Нор Up	1035	05/04/22	_	N/A	Good
Нор Up		17/05/22		N/A	Good
Нор Up		15/06/22	1 - 1	N/A	Good
Festool Plunge Saw	1401	17/05/22		29/12/22	Good
Battery Dewalt chopsaw	1409	23/05/22		N/A	Good
Battery Dewalt planer	1410	23/05/22	6	N/A	Good
Battery Dewalt skillsaw	1406	23/05/22	1	N/A	Good
Battery Dewalt jigsaw	1408	23/05/22	340	N/A	Good
Battery Dewalt router	1407	23/05/22	9	N/A	Good
110V transformer	178	26/09/22		26/12/22	Good
110V transformer	1443	30/09/22	- ,	30/12/22	Good
110V transformer	1348	12/10/22		12/01/23	Good

	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 2 of 1
--	-------------------	-------------	-----	--	--	-------------



## WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE:

**REPTON GARDENS** 

**COMPILED & CHECKED BY:** 

Slav Simonovic

**WEEK ENDING: 16/10/2022** 

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments	
TOOLBOX	7A	05/09/22		N/A	*1	
ГООLВОХ	14A	05/09/22		N/A		
BOSCH PLANER	905	05/09/22		02/12/22	Good working order	
UST EXTRACTOR	1359	05/09/22		02/12/22	Good working order	
MAKITA JIGSAW	1370	05/09/22		02/12/22	Good working order	
OSCH HAMMER DRILL	1329	05/09/22		02/12/22	Good working order	
DEWALT CHOPSAW	690	05/09/22		02/12/22	Good working order	
MAKITA SKILLSAW	706	05/09/22		02/12/22	Good working order	
10V EXTENSION LEAD	211	05/09/22		02/12/22	Good working order	
10V EXTENSION LEAD	0020	05/09/22	* * * * * * * * * * * * * * * * * * *	02/12/22	Good working order	
10V EXTENSION LEAD	0021	05/09/22		02/12/22	Good working order	
10V EXTENSION LEAD	0022	05/09/22	*	02/12/22	Good working order	
ESTOOL SKILL SAW	1392	06/09/22		02/12/22	Good working order	
LOV SPLITTER BOX	63150	08/09/22		02/12/22	Good working order	
OP UP	0023	08/09/22		N/A	Good working order	
SCUIT CUTTER	229	22/09/22		22/12/22	Good working order	
ODIUM STEP	PS30	30/09/22		N/A	Good working order	
ODIUM STEP	PS04	30/09/22		N/A	Good working order	
ASK LIGHT	28A	22/09/22	207-	22/12/22	Good working order	
	- 1775 - 1776 -	3415				

DOCUMENT REFERENCE:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE:	07/02/2013 01/03/2018	Page 1 of 1
---------------------	-------------------	-------------	-----	----------------	--------------------------	-------------



# WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 21m

COMPILED & CHECKED BY: J. Wray / D. Sanders

**WEEK ENDING: 16.10.22** 

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	04.10.21		N/A	
Long Pallet truck	1422	04.10.21		N/A	
Short Pallet truck	1442	01/06/22	214 5	N/A	
Delta Deck	1402	04.10.21		N/A	
Delta Deck (small)	1414	16.05.22		N/A	
Delta Deck (small)	1415	16.05.22		N/A	
Delta Deck	1425	14.07.22		N/A	
Delta Deck	1426	14.07.22		N/A	
Нор Up	1438	20.09.22		N/A	
Нор Up	1439	20.09.22		N/A	
Нор Up	1440	20.09.22		N/A	
Hop Up	1441	20.09.22		N/A	
Нор Up	979	28.09.22		N/A	
Нор Up	1018	28.09.22		N/A	
Toolbox	1340	04.10.21		N/A	located on level 9
Toolbox	11A	04.10.21		N/A	located on level 3
Toolbox	32A	04.10.21		N/A	located on level 3
Toolbox	1423	04.10.21		N/A	located on level 4
Toolbox	A2	24.03.22		N/A	located on level 3
Toolbox	L17	06/04/22		N/A	located on level 3
Toolbox	8A	16.05.22		N/A	located on level 4
Toolbox	1424	16.05.22		N/A	located on level 3
Toolbox .	1341	16.05.22		N/A	located on level 4
Toolbox	1342	03.08.22		N/A	located on level 7
Toolbox	4A	20.09.22		N/A	
110V Leads Numbers : 83,0009,0008,1225,1392	See across	04.10.21		12.11.22	471 DEFECTIVE – THROWN AWAY
110V Leads Numbers : 0006 , 1284 , 0001 , 1344	See	17.03.22		12.11.22	The second secon
Bosch Hammer drill	934	04.10.21		12.11.22	
Bosch pistol drill	888	04.10.21		12.11.22	
Makita Router	959	24.03.22		12.11.22	
Makita Router	1337	03.08.22		12.11.22	

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE:	07/02/2013 01/03/2018	Page <b>1</b> of <b>1</b>
--	-------------------	-------------	-----	---------------------------------------	--------------------------	---------------------------



page -	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			<b>3</b>	
			10		
Annual to the second of the second				2701	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
VI. CONTRACTOR AND					
	- Lori				a garage
L Frank				3 - 1× 1	8 -
	- A	1 1 1			
		0	0	, i	
				- 1 2	
Dewalt Battery Planner	To be checked	20.09.22		Ja	Testing - New ID no to be marked on sit - check with Joe which he has?
a x 5 x 5 x	1429 or 1430			??.??.??	Inc battery & charger - Needs Pat
Dewalt Battery Skill Saw	checked	20.09.22			- check with Joe which he has?
	1435 or 1436 To be		- 7.	??.??.??	Inc battery & charger - Needs Pat Testing - New ID no to be marked on site
Dewalt Battery Router	checked	20.09.22	7	22.22.22	- check with Joe which he has?
	To be				Testing - New ID no to be marked on site
Dewait Dattel & 118 Daw	1431 or 1432	20.03.22		??.??.??	Inc battery & charger - Needs Pat
Dewalt Battery Jig Saw	To be checked	20.09.22	) 	=	Testing - New ID no to be marked on site - check with Joe which he has?
	1427 or 1428	F 1-, 4		??.??.??	Inc battery & charger - Needs Pat
Dewalt Battery Mitre Saw	checked	20.09.22			- check with Joe which he has?
	1433 or 1434 To be			??.??.??	Inc battery & charger - Needs Pat Testing - New ID no to be marked on site
Dewalt Battery Task Light Charger	1421	23.05.22	-	12.11.22	
Dewalt Battery Task Light	1419	16.05.22	1 .	N/A	Inc battery
Dewalt Battery Task Light	1418	16.05.22		N/A	Inc battery
Dewalt Battery Task Light	1417	16.05.22		N/A	Inc battery
12v Caulking Gun & Charger	1437	20.09.22		??.??.??	Needs Pat Testing
12v Caulking Gun & Charger	1416	16.05.22		12.11.22	1
	×	BATTERY OP	ERATED TOOLS	5	
Dewalt Chop Saw	814	03.08.22		15.12.21	Needs Pat Testing
Dewalt Chop Saw	334	03.08.22		12.11.22	
Makita Jigsaw	137	???????	17/05/22	30.10.22	TAKEN BY JOE TO MLGH
Makita Skill Saw	1413	24.03.22		12.11.22	
Plastic bench stools	???	17.03.22	7 5 7	N/A	MISSING AT PRESENT (1 NO FOUND)
Paslode Straight pin gun	1382	28.09.22		N/A	
Paslode Straight pin gun	169	17.03.22		N/A	
Paslode Straight pin gun	72	17.03.22		N/A	13 13
Dust Extractor	1303	28.09.22	100		Needs Pat Testing
Dust Extractor	1247	28.09.22		17.04.22 23.09.21	Needs Pat Testing
Dust Extractor	1214	28.09.22	Description of the second	29.09.21	Needs Pat Testing
Dust Extractor	1344	24.03.22	1	12.11.22	500 mm m m m m m m m m m m m m m m m m m
Festool Router	VB001 (1967)	03.08.22	-2kg x	1	Owned by Vegas
		747		12.11.22	Ourned by Verse

DOCUMENT REFERENCE: SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE:	07/02/2013 01/03/2018	Page <b>2</b> of <b>1</b>	
------------------------------------	-------------	-----	---------------------------------------	--------------------------	---------------------------	--