



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: Hoxton Hotel

COMPILED & CHECKED BY:

A.Kulsinskas

WEEK ENDING 30/10/22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

<u>Plant Item</u>	<u>I.D. No.</u>	<u>On Site Date</u>	<u>Off Site Date</u>	<u>Test Expiry Date</u>	<u>Condition of items/ other comments</u>
Printer Epson	1405	10/05/22		29/12/22	Good
Toolbox	7A	25/04/22		N/A	Good
Toolbox (Rama)	1A	25/04/22		N/A	Good
Toolbox (Tibor)	16	26/04/22		N/A	Good
Toolbox (small ½)		06/06/22		N/A	Good
Toolbox (Gena)	A10	15/06/22		N/A	Good
Toolbox (Alex)	9A	15/06/22		N/A	Good
Toolbox (Fixings)	1026	20/06/22		N/A	Good
Makita Hammer drill	330	26/04/22		29/12/22	Good
Makita Hammer drill	361	14/09/22		14/12/22	Good
Bosch Hammer drill	941	14/09/22		14/12/22	Good
Metabolo pistol drill	758	26/04/22		17/01/23	Good
Milwaukee Mastic gun	1412	02/05/22		N/A	Good
110v Lead	0014	25/04/22		29/12/22	Good
110v Lead	0015	25/04/22		29/12/22	Good
110v Lead	0016	25/04/22		12/12/22	Good
110v Lead	0017	25/04/22		29/12/22	Good
110v Lead	0004	20/06/22		12/12/22	Good
110v Lead	1010a	04/07/22		29/12/22	Good
110v Lead	1267	04/07/22		29/12/22	Good
110v splitter box	238A	25/04/22	28/10/22	29/12/22	Sent back to RCL Office
110v splitter box	930	20/06/22	28/10/22	12/12/22	Sent back to RCL Office
110v splitter box	684	17/05/22	28/10/22	29/12/22	Sent back to RCL Office
110v splitter box	643	20/06/22		29/12/22	Good
110v splitter box	758	04/07/22		29/12/22	Good
110v splitter box	1368	04/07/22	28/10/22	29/12/22	Sent back to RCL Office
Task Light	34	25/04/22		29/12/22	Good
Task Light	1309	25/04/22	28/10/22	29/12/22	Sent back to RCL Office
Task Light	34	20/06/22	28/10/22	12/12/22	Sent back to RCL Office
Task Light	1306	21/07/22		17/01/23	Good
Task Light	29	21/07/22	28/10/22	17/01/23	Sent back to RCL Office
Task Light	31	21/07/22	28/10/22	17/01/23	Sent back to RCL Office

Dewalt Router	1361	25/05/22		29/12/22	Good
Dewalt Router	1357	25/05/22		29/12/22	Good
Green A Frame trolley		26/04/22		N/A	Good
Dewalt chopsaw	795	25/04/22	28/10/22		Tool repaired and sent to RCL Office.
Dewalt Chop saw	989	11/05/22		29/12/22	Good
Makita Chopsaw	785	09/08/22		09/11/22	Good
Makita planer	758	04/07/22		29/12/22	Good
Paslode 2 nd fix gun angled	1014	25/04/22		N/A	Good
Paslode 2 nd fix gun straight	529	25/04/22		N/A	Good
Paslode 2 nd fix gun straight	1255	20/06/22		N/A	Good
Chain mortiser	673	24/08/22	28/10/22	24/11/22	Sent back to RCL Office
Dust extractor	1304	25/04/22	28/10/22	29/12/22	Sent back to RCL Office
Dust extractor	1420	25/04/22		29/12/22	Good
Dust extractor	1242	17/05/22	28/10/22	29/12/22	Sent back to RCL Office
Dust extractor	1264	15/06/22		12/12/22	Good
Dust extractor	1241	15/06/22	28/10/22	12/12/22	Sent back to RCL Office
Hop Up	1035	05/04/22		N/A	Good
Hop Up	blue	17/05/22	28/10/22	N/A	Sent back to RCL Office
Hop Up	1017	15/06/22	28/10/22	N/A	Sent back to RCL Office
Festool Plunge Saw	1401	17/05/22		29/12/22	Good
Battery Dewalt chopsaw	1409	23/05/22		N/A	Good
Battery Dewalt planer	1410	23/05/22		N/A	Good
Battery Dewalt skillsaw	1406	23/05/22		N/A	Good
Battery Dewalt jigsaw	1408	23/05/22		N/A	Good
Battery Dewalt router	1407	23/05/22		N/A	Good
110V transformer	178	26/09/22		26/12/22	Good
110V transformer	1443	30/09/22		30/12/22	Good
110V transformer	1348	12/10/22		12/01/23	Good



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 21m

COMPILED & CHECKED BY: J. Wray / K. Kulsinskas

WEEK ENDING: 30.10.22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	04.10.21		N/A	
Long Pallet truck	1422	04.10.21		N/A	
Short Pallet truck	1442	01/06/22		N/A	
Delta Deck	1402	04.10.21		N/A	
Delta Deck (small)	1414	16.05.22		N/A	
Delta Deck (small)	1415	16.05.22		N/A	
Delta Deck	1425	14.07.22		N/A	
Delta Deck	1426	14.07.22		N/A	
Hop Up	1438	20.09.22		N/A	
Hop Up	1439	20.09.22		N/A	
Hop Up	1440	20.09.22		N/A	
Hop Up	1441	20.09.22		N/A	
Hop Up	979	28.09.22		N/A	
Hop Up	1018	28.09.22		N/A	
Toolbox	1340	04.10.21		N/A	located on level 9
Toolbox	11A	04.10.21		N/A	located on level 3
Toolbox	32A	04.10.21		N/A	located on level 3
Toolbox	1423	04.10.21		N/A	located on level 4
Toolbox	A2	24.03.22		N/A	located on level 3
Toolbox	L17	06/04/22		N/A	located on level 3
Toolbox	8A	16.05.22		N/A	located on level 4
Toolbox	1424	16.05.22		N/A	located on level 3
Toolbox	1341	16.05.22		N/A	located on level 4
Toolbox	1342	03.08.22		N/A	located on level 7
Toolbox	4A	20.09.22		N/A	
110V Leads Numbers : 83 , 0009 , 0008 , 1225 , 1392	See across	04.10.21		12.11.22	471 DEFECTIVE – THROWN AWAY
110V Leads Numbers : 0006 , 1284 , 0001 , 1344	See across	17.03.22		12.11.22	
Bosch Hammer drill	934	04.10.21		12.11.22	
Bosch pistol drill	888	04.10.21		12.11.22	
Makita Router	959	24.03.22		12.11.22	
Makita Router	1337	03.08.22		12.11.22	



BATTERY OPERATED TOOLS