



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: REPTON GARDENS

COMPILED & CHECKED BY: Slav Simonovic

WEEK ENDING: 18/12/2022

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
TOOLBOX	7A	29/11/22		N/A	
TOOLBOX	14A	29/11/22		N/A	
BOSCH PLANER	905	29/11/22		29/11/22	Good working order
DUST EXTRACTOR	1241	29/11/22		29/11/22	Good working order
MAKITA JIGSAW	1370	29/11/22		29/11/22	Good working order
BOSCH HAMMER DRILL	1329	29/11/22		29/11/22	Good working order
DEWALT CHOPSAW	621	29/11/22		29/11/22	Good working order
110V EXTENSION LEAD	211	29/11/22		29/11/22	Good working order
110V EXTENSION LEAD	0020	29/11/22		29/11/22	Good working order
110V EXTENSION LEAD	0022	29/11/22		29/11/22	Good working order
110V SPLITTER BOX	63150	29/11/22		29/11/22	Good working order
HOP UP	0023	08/09/22		N/A	
BISCUIT CUTTER	229	29/11/22		29/11/22	Good working order
PODIUM STEP	PS30	29/11/22		N/A	Good working order
LED TRIPOD LIGHT	1360	30/11/22		29/11/22	Good working order
TRIPOD LIGHT	0024	30/11/22		29/11/22	Good working order
BOSCH PISTOL DRILL	971	29/11/22		29/11/22	Good working order
4 STANLEY TRESTLES		29/11/22		N/A	NEW
2 SACKERS		29/11/22		N/A	NEW
PASLODE 2 nd . FIX	21905	05/12/22		N/A	Faulty / NOT IN USE
A - FRAME		29/11/22		N/A	



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 21m

COMPILED & CHECKED BY: J. Wray / K. Kulsinskas

WEEK ENDING: 18.12.22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	04.10.21		N/A	
Long Pallet truck	1422	04.10.21	16.12.22	N/A	Collected by Joe
Short Pallet truck	1442	01/06/22	16.12.22	N/A	Collected by Joe
Delta Deck	1402	04.10.21	16.12.22	N/A	Collected by Joe
Delta Deck	1426	14.07.22	16.12.22	N/A	Collected by Joe
Hop Up	1438	20.09.22		N/A	
Hop Up	1439	20.09.22		N/A	
Hop Up	979	28.09.22		N/A	
Hop Up	1018	28.09.22		N/A	
Toolbox	1340	04.10.21		N/A	
Toolbox	11A	04.10.21	16.12.22	N/A	Collected by Joe
Toolbox	32A	04.10.21		N/A	
Toolbox	1423	04.10.21		N/A	
Toolbox	A2	24.03.22		N/A	
Toolbox	L17	06/04/22		N/A	
Toolbox	8A	16.05.22	16.12.22	N/A	Collected by Joe
Toolbox	1424	16.05.22		N/A	
Toolbox	1341	16.05.22		N/A	
Toolbox	1342	03.08.22		N/A	
Toolbox	4A	20.09.22	16.12.22	N/A	Collected by Joe
110V Leads Numbers : 83 , 0009 , 0008 , 1225 , 1392	See across	04.10.21		14.02.23	471 DEFECTIVE – THROWN AWAY
110V Leads Numbers : 0006 , 1284 , 0001 , 1344	See across	17.03.22		14.02.23	
Bosch Hammer drill	934	04.10.21		14.02.23	
Bosch pistol drill	888	04.10.21		14.02.23	
Makita Router	959	24.03.22		14.02.23	
Makita Router	1337	03.08.22		14.02.23	
Dewalt Router	1367	03.08.22		14.02.23	
Festool Router	VB001 (1967)	03.08.22		14.02.23	Owned by Vegas
Dust Extractor	1344	24.03.22		14.02.23	
Dust Extractor	1214	28.09.22		14.02.23	
Dust Extractor	1303	28.09.22		14.02.23	



DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE:	07/02/2013 01/03/2018	Page 2 of 1
--	-------------------	-------------	-----	---------------------------------------	--------------------------	-------------