



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 21m

COMPILED & CHECKED BY: K. Kulsinkas

WEEK ENDING: 15.01.23

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	04.10.21	13.01.23	N/A	
Hop Up	1438	20.09.22	13.01.23	N/A	
Hop Up	1439	20.09.22		N/A	
Hop Up	979	28.09.22		N/A	
Hop Up	1018	28.09.22		N/A	
Toolbox	1340	04.10.21		N/A	
Toolbox	32A	04.10.21		N/A	
Toolbox	1423	04.10.21		N/A	
Toolbox	A2	24.03.22		N/A	
Toolbox	L17	06/04/22		N/A	
Toolbox	1424	16.05.22		N/A	
Toolbox	1341	16.05.22		N/A	
Toolbox	1342	03.08.22		N/A	
110V Leads Numbers : 83 , 0009 , 0008 , 1225 , 1392	See across	04.10.21		14.02.23	471 DEFECTIVE – THROWN AWAY
110V Leads Numbers : 0006 , 1284 , 0001 , 1344	See across	17.03.22		14.02.23	
Bosch Hammer drill	934	04.10.21		14.02.23	
Bosch pistol drill	888	04.10.21		14.02.23	
Makita Router	959	24.03.22		14.02.23	
Makita Router	1337	03.08.22		14.02.23	
Dewalt Router	1367	03.08.22		14.02.23	
Festool Router	VB001 (1967)	03.08.22		14.02.23	Owned by Vegas
Dust Extractor	1344	24.03.22		14.02.23	
Dust Extractor	1214	28.09.22	13.01.23	14.02.23	
Dust Extractor	1303	28.09.22	13.01.23	14.02.23	
Dust Extractor	1359	27.10.22		14.02.23	
Dust Extractor	1363	24/11/22	13.01.23	25.02.23	REQUESTED BY VEGAS ?
Paslode Straight pin gun	72	17.03.22		N/A	
Paslode Straight pin gun	169	17.03.22		N/A	
Plastic bench stools	???	17.03.22		N/A	MISSING AT PRESENT (1 NO FOUND)
Makita Jigsaw	137	???????	17.05.22	30.10.22	TAKEN BY JOE TO MLGH
Dewalt Chop Saw	334	03.08.22	13.01.23	14.02.23	



BATTERY OPERATED TOOLS

DOCUMENT REFERENCE: DOCUMENT OWNER:	SIT-FM-011 DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE:	07/02/2013 01/03/2018	Page 2 of 1
--	-------------------	-------------	-----	---------------------------------------	--------------------------	-------------