



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 21m

COMPILED & CHECKED BY: K. Kulsinskas

WEEK ENDING: 29.01.23

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	04.10.21		N/A	
Hop Up	1439	20.09.22		N/A	
Hop Up	979	28.09.22		N/A	
Toolbox	1340	04.10.21		N/A	
Toolbox	32A	04.10.21		N/A	
Toolbox	1423	04.10.21		N/A	
Toolbox	A2	24.03.22		N/A	
Toolbox	L17	06/04/22		N/A	
Toolbox	1424	16.05.22		N/A	
Toolbox	1341	16.05.22		N/A	
Toolbox	1342	03.08.22		N/A	
Toolbox	25A	19/01/23		N/A	
110V Leads Numbers : 83 , 0009 , 0008 , 1225 , 1392	See across	04.10.21		14.02.23	
110V Leads Numbers : 0006 , 1284 , 0001 , 1344	See across	17.03.22		14.02.23	
Bosch Hammer drill	934	04.10.21		14.02.23	
Bosch pistol drill	888	04.10.21		14.02.23	
Makita Router	959	24.03.22		14.02.23	
Makita Router	1337	03.08.22		14.02.23	
Dewalt Router	1367	03.08.22		14.02.23	
Festool Router	VB001 (1967)	03.08.22		14.02.23	Owned by Vegas
Dust Extractor	1344	24.03.22		14.02.23	
Dust Extractor	1359	27.10.22		14.02.23	
Paslode Straight pin gun	72	17.03.22		N/A	
Paslode Straight pin gun	169	17.03.22		N/A	
Plastic bench stools	???	17.03.22		N/A	MISSING AT PRESENT (1 NO FOUND)
Makita Jigsaw	137	???????	17.05.22	30.10.22	TAKEN BY JOE TO MLGH
110 v Splitter Box	1253	24.11.22		25.02.23	REQUESTED BY VEGAS ?
110 v Splitter Box	1404	24.11.22		25.02.23	REQUESTED BY VEGAS ?
Makita Planner	942	09.12.22		12.03.23	
Festool Skill Saw	1392	November ?		12.02.23	REQUESTED BY KES ?



BATTERY OPERATED TOOLS					
12v Caulking Gun & Charger	1416	16.05.22		14.02.23	
12v Caulking Gun & Charger	1437	20.09.22		14.02.23	
Dewalt Battery Task Light	1418	16.05.22		N/A	BATTERY ONLY MISSING FROM BOX 8A
Dewalt Battery Task Light Charger	1421	23.05.22		14.02.23	
Dewalt Battery Mitre Saw	1433	20.09.22		14.02.23	Inc battery & charger
Dewalt Battery Jig Saw	1427	20.09.22		14.02.23	Inc charger – Battery sent to MLG 18/01
Dewalt Battery Router	1431	20.09.22		14.02.23	Inc battery & charger
Dewalt Battery Skill Saw	1435	20.09.22		14.02.23	BATTERY ONLY MISSING FROM BOX 8A



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: Woking.

COMPILED & CHECKED BY: Slav Simonovic

WEEK ENDING: 29/01/23

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
TOOLBOX	11A	19/01/23		N/A	
DUST EXTRACTOR	1214	19/01/23		14/03/23	Good working order
DEWALT CHOPSAW	334	19/01/23		14/03/23	Good working order
PASLODE GUN 2 ND . FIX	1255	19/01/23		N/A	
110 V EXTENSION LEAD	---	19/01/23		14/03/23	
110 V TRANSFORMER	---	19/01/23		14/03/23	