



WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE:

VSW – WOKI - 03

COMPILED & CHECKED BY:

J.Wray / K.Kulsinskas

WEEK ENDING

06/02/22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
Toolbox (Bin Stores level 01)	7A	20/02/2020		N/A	Good Condition
Toolbox (carpark level 02)	14A	02/03/2020		N/A	Good Condition
Toolbox (carpark level 03)	1A	02/03/2020		N/A	Good Condition
Toolbox (carpark level 03)	16A	02/03/2020		N/A	Good Condition
Toolbox (carpark level 02)	23A	12/06/2020		N/A	Hydraulic Arms Faulty
Toolbox (carpark level 03)	17	15/07/2020		N/A	Good Condition
Toolbox (small) in office	1026	22/06/2020		N/A	Good Condition
Toolbox (RCP Ground core 02)	25A	12/06/2020		N/A	Good Condition
Toolbox (RCP Ground core 02)	8A	15/07/2020		N/A	Good Condition
Toolbox (Tower Basement)	???	01/09/2021		N/A	Good Condition
Hop Up	1035	20/11/2020		N/A	Good Condition
2 nd Fix Paslode Gun	1382	07/10/2020		N/A	Good Condition
2 nd Fix Paslode Gun	991	01/04/2020		N/A	Good Condition
A Frame	Big Blue	04/06/2020		N/A	Good Condition
110v Lead	1266	20/02/2020		17/04/2022	Good Condition
110v Lead	1253	20/02/2020		17/04/2022	Good Condition
110v Lead	1394	20/10/2020		17/04/2022	Good Condition
110v Lead	1395	20/10/2020		17/04/2022	Good Condition
110v Lead	1396	20/10/2020		17/04/2022	Good Condition
110v Lead	13	20/02/2020		17/04/2022	Good Condition
110v Lead	1247	20/02/2020		17/04/2022	Good Condition
110v Lead	1263	20/02/2020		17/04/2022	Good Condition
110v Lead	12	20/02/2020		17/04/2022	Good Condition
110v Splitter Box	246	05/10/2020		17/04/2022	Good Condition
Dust Control Extractor	1363	12/06/2020		17/04/2022	Good Condition
Dust Control Extractor	1353	13/10/2020		17/04/2022	Good Condition
Dust Control Extractor	1343	20/10/2020		17/04/2022	Good Condition
Makita Router ¼	1208	05/10/2020		17/04/2022	Good Condition
DeWalt Router ¼	1361	26/07/2021		17/04/2022	Good Condition
DeWalt Chop saw	989	27/04/2021		17/04/2022	Good Condition
DeWalt Chop saw	785	27/04/2021		17/04/2022	Good Condition
Makita Jigsaw	1276	20/02/2020		17/04/2022	Good Condition
Makita Jigsaw	1370	26/07/2021		17/04/2022	Good Condition
Makita Skill saw	622	20/02/2020		17/04/2022	Good Condition
Festool saw	1385	07/10/2020		17/04/2022	Good Condition
Festool Guide	R1	07/10/2020		N/A	Good Condition
Festool Guide	R2	07/10/2020		N/A	Good Condition
Makita Planer	751	23/02/2021		17/04/2022	Good Condition
Makita Planer	161	05/10/2020		17/04/2022	Good Condition
Makita Multi Tool	1280	07/10/2020		17/04/2022	Good Condition
Makita Cold Cutter	1349	27/05/2021		17/04/2022	Good Condition
Makita Hammer Drill	361	20/10/2020		17/04/2022	Good Condition
Bosch Hammer Drill	941	26/01/2022		26/04/2022	Good Condition
Bosch Hammer Drill	894	26/01/2022		26/04/2022	Good Condition
Makita Hammer Drill	1379	26/01/2022		26/04/2022	Chuck not working properly

DOCUMENT REFERENCE:	SIT-FM-011	VERSION NO:	1.1	CREATION DATE:	07/02/2013	Page 1 of 1
DOCUMENT OWNER:	DAS			LAST REVISION DATE:	04/07/2013	
				NEXT REVIEW DATE:	07/02/2014	