



# WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

**SITE: 25 Cannon Street**

**COMPILED & CHECKED BY: A. Kulsinskas**

**WEEK ENDING 06/03/22**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| <u>Plant Item</u>               | <u>I.D. No.</u> | <u>On Site Date</u> | <u>Off Site Date</u> | <u>Test Expiry Date</u> | <u>Condition of items/<br/>other comments</u> |
|---------------------------------|-----------------|---------------------|----------------------|-------------------------|---|
| Printer Epson                   | 1405            | 22/09/21            |                      | 10/04/22                | Good  |
| Toolbox                         | 3A              | 19/07/21            |                      | N/A                     | Good  |
| Toolbox                         | 10A             | 19/07/21            |                      | N/A                     | Good  |
| Toolbox                         | 41A             | 19/07/21            |                      | N/A                     | Good  |
| Toolbox                         | 1341            | 06/10/21            |                      | N/A                     | Good  |
| Toolbox                         | 50              | 06.10.21            |                      | N/A                     | Good  |
| Toolbox (small)                 | 4887            | 05/11/21            |                      | N/A                     | Good  |
| 110v Extension Lead             | 2001            | 19/07/21            |                      | 10/04/22                | Good  |
| 110v Extension Lead             | 2002            | 19/07/21            |                      | 10/04/22                | Good  |
| 110v Extension Lead             | 2003            | 19/07/21            |                      | 10/04/22                | Good  |
| 110v Extension Lead             | 2004            | 19/07/21            |                      | 10/04/22                | Good  |
| 110V Splitter box               | 643             | 19/07/21            |                      | 10/04/22                | Good  |
| 110V Splitter box               | 758             | 05/11/21            |                      | 10/04/22                | Good  |
| Makita Multi tool               | 1380            | 06/10/21            |                      | 10/04/22                | Good  |
| Small Makita Skill Saw          | 1043            | 19/07/21            |                      | 10/04/22                | Good  |
| Festool plunge saw              | 1401            | 26/10/21            |                      | 10/04/22                | Good  |
| Dust Extractor                  | 1265            | 19/07/21            |                      | 10/04/22                | Good  |
| Dust Extractor                  | 1242            | 26/10/21            |                      | 10/04/22                | Good  |
| Makita Planer                   | 942             | 19/07/21            |                      | 10/04/22                | Good  |
| 2 <sup>nd</sup> fix Paslode Gun | 1255            | 19/07/21            |                      | 10/04/22                | Good  |
| DeWalt Chop Saw                 | 676             | 19/07/21            |                      | 10/04/22                | Good  |
| Bosch Jigsaw                    | 184             | 19/07/21            |                      | 10/04/22                | Good  |
| Bosch Hammer Drill              | 1329            | 19/07/21            |                      | 10/04/22                | Good  |
| Dewalt ¼ Router                 | 1403            | 19/07/21            |                      | 10/04/22                | Good  |
| Podium Steps                    | SW03            | 19/07/21            |                      | N/A                     | Good  |
| A Frame trolley                 | 5               | 21/09/21            |                      | N/A                     | Good  |
| Desk                            | No ID           | 22/07/21            |                      | N/A                     | Good  |
| Desk                            | No ID           | 22/07/21            |                      | N/A                     | Good  |
| Chair                           | No ID           | 22/07/21            |                      | N/A                     | Good  |
| Chair                           | No ID           | 22/07/21            |                      | N/A                     | Good  |

|                     |            |             |     |                     |            |             |
|---------------------|------------|-------------|-----|---------------------|------------|-------------|
| DOCUMENT REFERENCE: | SIT-FM-011 | VERSION NO: | 1.1 | CREATION DATE:      | 07/02/2013 | Page 1 of 1 |
| DOCUMENT OWNER:     | DAS        |             |     | LAST REVISION DATE: | 04/07/2013 |             |
|                     |            |             |     | NEXT REVIEW DATE:   | 07/02/2014 |             |



# WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

**SITE:**

VSW – WOKI - 03

**COMPILED & CHECKED BY:**

K.Kulsinskas & J.Wray

**WEEK ENDING**

06/03/22

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| Plant Item                      | I.D. No. | On Site    | Off Site   | Test Expiry | Condition of items/<br>other comments |
|---------------------------------|----------|------------|------------|-------------|---------------------------------------|
|                                 |          | Date       | Date       | Date        |                                       |
| Toolbox (Bin Stores level 01)   | 7A       | 20/02/2020 |            | N/A         | Good Condition                        |
| Toolbox (carpark level 02)      | 14A      | 02/03/2020 |            | N/A         | Good Condition                        |
| Toolbox (carpark level 03)      | 1A       | 02/03/2020 |            | N/A         | Good Condition                        |
| Toolbox (carpark level 03)      | 16A      | 02/03/2020 |            | N/A         | Good Condition                        |
| Toolbox (carpark level 02)      | 23A      | 12/06/2020 |            | N/A         | Hydraulic Arms Faulty                 |
| Toolbox (carpark level 03)      | 17       | 15/07/2020 |            | N/A         | Good Condition                        |
| Toolbox (small) in office       | 1026     | 22/06/2020 |            | N/A         | Good Condition                        |
| Toolbox (moved outside by SRM)  | 25A      | 12/06/2020 |            | N/A         | Good Condition / By Gate 1            |
| Toolbox (moved outside by SRM)  | 8A       | 15/07/2020 |            | N/A         | Good Condition / By Gate 1            |
| Toolbox (Tower Basement)        | ???      | 01/09/2021 |            | N/A         | Good Condition                        |
| Hop Up                          | 1035     | 20/11/2020 |            | N/A         | Good Condition                        |
| 2 <sup>nd</sup> Fix Paslode Gun | 1382     | 07/10/2020 |            | N/A         | Good Condition                        |
| 2 <sup>nd</sup> Fix Paslode Gun | 991      | 01/04/2020 |            | N/A         | Good Condition                        |
| A Frame                         | Big Blue | 04/06/2020 |            | N/A         | Good Condition                        |
| 110v Lead                       | 1266     | 20/02/2020 |            | 17/04/2022  | Good Condition                        |
| 110v Lead                       | 1253     | 20/02/2020 |            | 17/04/2022  | Good Condition                        |
| 110v Lead                       | 1394     | 20/10/2020 |            | 17/04/2022  | Good Condition                        |
| 110v Lead                       | 1395     | 20/10/2020 |            | 17/04/2022  | Good Condition                        |
| 110v Lead                       | 1396     | 20/10/2020 |            | 17/04/2022  | Good Condition                        |
| 110v Lead                       | 13       | 20/02/2020 |            | 17/04/2022  | Good Condition                        |
| 110v Lead                       | 1247     | 20/02/2020 |            | 17/04/2022  | Good Condition                        |
| 110v Lead                       | 1263     | 20/02/2020 |            | 17/04/2022  | Good Condition                        |
| 110v Lead                       | 12       | 20/02/2020 |            | 17/04/2022  | Good Condition                        |
| 110v Splitter Box               | 246      | 05/10/2020 |            | 17/04/2022  | Good Condition                        |
| Dust Control Extractor          | 1363     | 12/06/2020 |            | 17/04/2022  | Good Condition                        |
| Dust Control Extractor          | 1353     | 13/10/2020 |            | 17/04/2022  | Good Condition                        |
| Dust Control Extractor          | 1343     | 20/10/2020 |            | 17/04/2022  | Good Condition                        |
| Makita Router ¼                 | 1208     | 05/10/2020 |            | 17/04/2022  | Good Condition                        |
| DeWalt Router ¼                 | 1361     | 26/07/2021 |            | 17/04/2022  | Good Condition                        |
| DeWalt Chop saw                 | 989      | 27/04/2021 |            | 17/04/2022  | Good Condition                        |
| DeWalt Chop saw                 | 785      | 27/04/2021 | 01/03/2022 | 17/04/2022  | BROKEN GUARD                          |
| DeWalt Chop saw                 | 621      | 01/03/2022 |            | 01/06/2022  | Good Condition                        |
| Makita Jigsaw                   | 1276     | 20/02/2020 |            | 17/04/2022  | Good Condition                        |
| Makita Jigsaw                   | 1370     | 26/07/2021 |            | 17/04/2022  | Good Condition                        |
| Makita Skill saw                | 622      | 20/02/2020 |            | 17/04/2022  | Good Condition                        |
| Festool saw                     | 1385     | 07/10/2020 |            | 17/04/2022  | Good Condition                        |
| Festool Guide                   | R1       | 07/10/2020 |            | N/A         | Good Condition                        |
| Festool Guide                   | R2       | 07/10/2020 |            | N/A         | Good Condition                        |
| Makita Planer                   | 751      | 23/02/2021 |            | 17/04/2022  | Good Condition                        |
| Makita Planer                   | 161      | 05/10/2020 |            | 17/04/2022  | Good Condition                        |
| Makita Multi Tool               | 1280     | 07/10/2020 |            | 17/04/2022  | Good Condition                        |
| Makita Cold Cutter              | 1349     | 27/05/2021 |            | 17/04/2022  | Good Condition                        |
| Makita Hammer Drill             | 361      | 20/10/2020 |            | 17/04/2022  | Good Condition                        |
| Bosch Hammer Drill              | 941      | 26/01/2022 |            | 26/04/2022  | Good Condition                        |
| Bosch Hammer Drill              | 894      | 26/01/2022 |            | 26/04/2022  | Good Condition                        |
| Makita Hammer Drill             | 1379     | 26/01/2022 | 01/03/2022 | 26/04/2022  | Chuck not working properly            |



## WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

**SITE: 21m**

**COMPILED & CHECKED BY: G BUCK**

**WEEK ENDING: 20.03.21**

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

| Plant Item                                  | I.D. No. | On Site Date | Off Site Date | Test Expiry Date | Condition of items/<br>other comments |
|---|----------|--------------|---------------|------------------|---------------------------------------|
| Bosch Hammer drill                          | 934      | 04.10.21     |               |                  |                                       |
| Bosch pistol drill                          | 888      | 04.10.21     |               |                  |                                       |
| AFrame                                      | NA       | 04.10.21     |               |                  |                                       |
| Pallet truck                                | NA       | 04.10.21     |               |                  |                                       |
| Delta Deck                                  | 1402     | 04.10.21     |               |                  |                                       |
| Box   | 1340     | 04.10.21     |               |                  |                                       |
| Box   | 11A      | 04.10.21     |               |                  |                                       |
| Box   | 32A      | 04.10.21     |               |                  |                                       |
| Box   | ??       | 04.10.21     |               |                  |                                       |
| Leads Numbers<br>83,471,0009,0008,1225,1392 |          | 04.10.21     |               |                  |                                       |
| Router                                      |          | 17.03.22?    |               |                  |                                       |
| Makita Chop saw                             | 620      | 17.03.22?    |               |                  |                                       |
| Dust Extractor                              | 1243     | 17.03.22?    |               |                  |                                       |
| Lead Numbers 0006,1284,0001                 |          | 17.03.22?    |               |                  |                                       |
| Junction box                                | 648      | 17.03.22?    |               |                  |                                       |
| Pasloide Straight pin gun                   | 72       | ???????      |               |                  | Which one broken?                     |
| Pasloide Straight pin gun                   | 169      | ???????      |               |                  | Which one broken?                     |
| Plastic bench stools                        |          | 17.03.22?    |               |                  |                                       |