



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 84 Moorgate

COMPILED & CHECKED BY: D Sanders

WEEK ENDING: 06.08.23

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	16/06/23		N/A	
Hop Up	1438	16/06/23		N/A	
Toolbox	1424	16/06/23		N/A	
Toolbox	L25	16/06/23		N/A	
Toolbox	32A	16/06/23		N/A	
Bosch Hammer drill	934	16/06/23		12/09/23	
Bosch pistol drill	888	16/06/23		12/09/23	
Dust Extractor	1241	16/06/23		12/09/23	
Plastic bench stools	NO NUMBER	16/06/23		N/A	
Extension Lead	00012	16/06/23		12/09/23	
Extension Lead	74	16/06/23		12/09/23	
Extension Lead	00013	16/06/23		12/09/23	
110 v Splitter Box	1404	16/06/23		12/09/23	
DeWalt 1/2 Router	891A	16/06/23		09/09/23	
Paslode	72	21/06/23		?	
Paslode	169	21/06/23		?	
Makita skillsaw	827	06/07/23		05/10/23	
DeWalt Chopsaw	786	17/07/23		17/10/23	
Scaffold Tower	03	10/07/23	02/08/23	N/A	Collected by Joe
Podium	1231A	28/07/23		N/A	
Podium	PS04	28/07/23		N/A	
Feststool skill saw	1392	November	02/08/23		

BATTERY OPERATED TOOLS

Dewalt Battery Router	1432	16/06/23		12/09/23	Inc battery & charger
Dewalt Battery Jig Saw	1428	16/06/23		12/09/23	Inc battery & charger
Dewalt Battery Planner	1430	16/06/23		12/09/23	Inc battery & charger
12v caulking gun	1437	02/08/23			



WEEKLY PLANT RETURN AND PLANT SAFETY CHECK

SITE: 21m

COMPILED & CHECKED BY: J. Wray & K. Kulsinkas

WEEK ENDING: 06.08.23

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
A Frame Trolley	393	04.10.21	02/08/23	N/A	Gone to 84 Moorgate
Toolbox	1340	04.10.21		N/A	
Toolbox	A2	24.03.22		N/A	
Toolbox	L17	06/04/22		N/A	
Toolbox	1342	03.08.22	05/07/23	N/A	Gone to Camden Hill Road job
Bosch Hammer drill	934	04.10.21		22.09.23	
Dust Extractor	1359	24.03.22		22.09.23	
Festool Skill Saw	1392	November?	02/08/23	22.09.23	Gone to 84 Moorgate
110 v Splitter Box	930	30/05/23		21/09/23	
Hop up	1018	02/08/23		N/A	

BATTERY OPERATED TOOLS

12v Caulking Gun & Charger	1437	20.09.22	02/08/23	22.09.23	Gone to 84 Moorgate
Dewalt Battery Task Light	1418	16.05.22		N/A	BATTERY ONLY MISSING FROM BOX 8A
Dewalt Battery Task Light Charger	1435	23.05.22		22.09.23	
Dewalt Battery Mitre Saw	1433	20.09.22		22.09.23	Inc battery & charger
Dewalt Battery Jig Saw	1427	20.09.22		22.09.23	Inc charger – Battery sent to MLG 18/01
Dewalt Battery Router	1431	20.09.22		22.09.23	Inc battery & charger
Dewalt Battery Skill Saw	1435	20.09.22		22.09.23	BATTERY ONLY MISSING FROM BOX 8A
Dewalt Battery Planner	1429	20.09.22		22.09.23	
Dewalt Battery Charger	1427	20.09.22		22.09.23	
Dewalt Battery Charger	1433	20.09.22		22.09.23	
Paslode straight pin gun	1382	?		N/A	
Dewalt multi tool	1450	26.06.23	02/08/23	22.09.23	Gone to CMS Job

WEEKLY PLANT RETURN

AND

PLANT SAFETY CHECK

SITE: 57 Campden Hill

COMPILED & CHECKED BY: K.Kulsinskas

WEEK ENDING: 06-08-23

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement without delay

[illegible]