

WEEKLY PLANT RETURN

AND PLANT SAFETY CHECK



SITE: Millennium Bridge

COMPILED & CHECKED BY: A.Kulsinskas

WEEK ENDING 08.06.25

Please ensure any defective tools are taken out of service immediately and sent for repair or replacement

Plant Item	I.D. No.	On Site Date	Off Site Date	Test Expiry Date	Condition of items/ other comments
Toolbox.	1424	18/10/24		N/A	Good condition
Toolbox	32A	06/05/25		N/A	Good condition
Extension lead	17	08/01/24		21/07/25	Good condition
Dust extractor	1420	18/10/24		21/07/25	Good condition
Festool plunge saw	1392	18/10/24		21/07/25	Good condition
2 nd fix Paslode Gun	1382	18/10/24		N/A	Good condition
Delta Deck work platform	1402	18/10/24		N/A	Good condition
Makita battery hammer drill+charger + 2 batteries	1514	18/10/24		21/07/25	Good condition
Dewalt battery	1436	18/10/24		N/A	Good condition
Dewalt Battery	1409	18/10/24		N/A	Good condition
Dewalt Router	1432	18/10/24		N/A	Good condition
Dewalt Battery Planer+Charger	1430	18/10/24		21/07/25	Good condition
Dewalt Battery light	1418	18/10/24		N/A	Good condition
Makita multi tool	1280	18/10/24		21/07/25	Good condition
A frame trolley yellow		18/10/24		N/A	Good condition
Dewalt battery chop saw	1433	04/02/25		N/A	Good condition
Dewalt battery skillsaw	1436	04/02/25		N/A	Good condition

DOCUMENT REFERENCE: SIT-FM-011 DOCUMENT OWNER: DAS	VERSION NO:	1.1	CREATION DATE: LAST REVISION DATE: NEXT REVIEW DATE:	07/02/2013 04/07/2013 07/02/2014	Page 1 of 2
--	-------------	-----	--	--	-------------